

ANIDIS 2007

XII CONVEGNO L'INGEGNERIA SISMICA IN ITALIA

sommari
relazioni ad invito
atti su DVD

PISA
POLO CARMIGNANI
10-14 GIUGNO 2007



REGIONE
TOSCANA



Università di Pisa
Dipartimento di
Ingegneria Strutturale

ASSOCIAZIONE NAZIONALE ITALIANA DI
INGEGNERIA SISMICA



Italian National Association of Earthquake Engineering

Università di Pisa



DIS – Dipartimento di
Ingegneria Strutturale

ASSOCIAZIONE NAZIONALE ITALIANA DI
INGEGNERIA SISMICA



Italian National Association of Earthquake Engineering

REGIONE
TOSCANA



XII Convegno ANIDIS

L'INGEGNERIA SISMICA IN ITALIA

SOMMARI
RELAZIONI AD INVITO
ATTI SU DVD

A cura di Franco Braga e Walter Salvatore
con la collaborazione di Elisabetta Alderighi, Aurelio Braconi, Luca Nardini

Pisa, Polo Carmignani
10-14 Giugno 2007

Convegno nazionale L'ingegneria sismica in Italia, 12., Pisa, 2007

L'ingegneria sismica in Italia : 12. convegno ANIDIS, Pisa, Polo Carmignani, 10-14 giugno 2007 : sonuari, relazioni ad invito, atti su dvd / a cura di Franco Braza e Walter Salvatore ; con la collaborazione di Elisabetta Alderighi, Aurelio Braconi, Luca Nardini
In testa al front.: Università di Pisa DIS - Dipartimento di ingegneria strutturale, Associazione nazionale italiana di ingegneria sismica ANIDIS, Regione Toscana

624.1762 (21.)

I. Ingegneria sismica - Congressi - Pisa - 2007 I. Braza, Franco II. Salvatore, Walter III. Alderighi, Elisabetta IV. Braconi, Aurelio V. Nardini VI. Associazione nazionale italiana di ingegneria sismica

CIP a cura del Sistema bibliotecario dell'Università di Pisa

EDIZIONI
plūs
pisa university
press

© Copyright 2007 by Edizioni Plus - Pisa University Press
Lungarno Pacinotti, 43
56126 Pisa
Tel. 050 2212056 - Fax 050 2212945
info-plus@edizioniplus.it
www.edizioniplus.it

In copertina: foto tratta da "Pisa e il suo territorio tra cartografia e vedutismo dal XV al XIX secolo.
La raccolta di Valentino Cai", Ed. Plus, Pisa

Fotocopie per uso personale del lettore possono essere effettuate nei limiti del 15% di ciascun volume/fascicolo di periodico dietro pagamento alla SIAE del canone previsto dall'art. 68, comma 4, della legge 22 aprile 1941 n. 633 ovvero dall'accordo stipulato tra SIAE, AIE, SNS e CNA, CONFARTIGIANATO, CONFEDILCOOPERAZIONE, CONFESERCENTI il 18 dicembre 2000.

Le riproduzioni per uso differente da quello personale sopracitato potranno avvenire solo a seguito di specifica autorizzazione rilasciata dagli aventi diritto.

COMITATO D'ONORE

Marcello Mauro, Presidente del Consiglio Superiore dei LL.PP.
Mauro Dolce, Direttore del Servizio Sismico Nazionale
Federico Gelli, Vice-Presidente della Regione Toscana
Paolo Fontanelli, Sindaco della Città di Pisa
Andrea Pieroni, Presidente della Provincia di Pisa
Marco Pasquali, Rettore dell'Università di Pisa
Emilio Vitale, Preside della Facoltà di Ingegneria di Pisa
Raffaele Sirica, Presidente del Consiglio Nazionale degli Architetti
Pietro Antonio De Paola, Presidente del Consiglio Nazionale dei Geologi
Paolo Stefanelli, Presidente del Consiglio Nazionale degli Ingegneri

COMITATO SCIENTIFICO

Antonio Borri, Università di Perugia
Franco Braga, Università di Roma La Sapienza, *Presidente*
Marcello Ciampoli, Università di Roma La Sapienza
Antonello De Luca, Università di Napoli
Alessandro De Stefano, Politecnico di Torino
Mario De Stefano, Università di Firenze
Mauro Dolce, Servizio Sismico Nazionale
Sergio Lagomarsino, Università di Genova
Domenico Liberatore, Università della Basilicata
Alessandro Martelli, ENEA Bologna – Università di Ferrara
Michele Maugeri, Università di Catania
Giorgio Monti, Università di Roma La Sapienza
Camillo Nuti, Università di Roma III
Tito Sanò, Servizio Sismico Nazionale
Luca Sanpaolesi, Presidente AICAP

COMITATO ORGANIZZATORE

Stefano Bennati, *Direttore del DIS*
Fabrizio Bianchi
Aurelio Braconi
Simona Burchi
Maurizio Ferrini, *Vice-Presidente*
Andrea Melozzi
Valeria Nannini, *Segretario*
Luca Nardini
Walter Salvatore, *Presidente*

CON LA COLLABORAZIONE DI:

Federazione Regionale degli Ordini degli Architetti della Toscana, Federazione Regionale degli Ordini degli Ingegneri della Toscana, Ordine dei Geologi della Toscana, Ordine degli Ingegneri della Provincia di Livorno, Ordine degli Ingegneri della Provincia di Lucca, Ordine degli Ingegneri della Provincia di Massa Carrara, Ordine degli Ingegneri della Provincia di Pisa, Ordine degli Architetti della Provincia di Lucca, Ordine degli Architetti della Provincia di Livorno

SPONSOR:



arcelor MITAL

SISMIC

ASSO.TRA.FIL.RETI
Associazione produttori acciaio trafilato a freddo, rete e traliccio elettrostatici

Calcestruzzi
Italcementi Group

Commissione Sismica
del C.I.S. (C.I.S. 1984) di Anzio

Promozione
Acciaio
CERI
Centro di Ricerca
"Previsione, Prevenzione e Controllo dei Rischi Geologici"

On site and laboratory investigation to assess material and structural damage on some churches hit by an earthquake

Anna Anzani, Luigia Binda, Lorenzo Cantini, Giuliana Cardani, Antonella Saisi, Cristina Tedeschi
Dipartimento di Ingegneria Strutturale, Politecnico di Milano, P.za Leonardo da Vinci, 32 – 20133 Milano, Italia

Keywords: churches, earthquake, failure mechanisms, masonry characterization

ABSTRACT:

At the end of 2004, an earthquake (5.2 Richter scale) hit the eastern part of the Lombardy Region in Northern Italy. No casualties occurred luckily, but many buildings were damaged and particularly affected was the vast patrimony of Churches. The authors were asked by various parishes to carry out a preliminary after earthquake investigation on 10 Churches and 2 rectories, carefully chosen to be representative of the total number existing. The aim was to assess the state of damage of the structures and the properties of the materials as a base for the preservation and repair projects. The investigation was carried out following the same procedure for all the Churches: archive documentary research, geometrical and crack pattern survey and interpretation, definition of the possible incipient collapse mechanisms, mechanical characterization of the masonry through flat-jack tests, use of sonic tests to define the density of the walls, individuation of the masonry section typology by sampling, ultrasonic tests on stone columns, vibration tests on tie rods, definition of mortar and stone properties sampled from the walls through chemical, physical and mechanical laboratory tests.

1 INTRODUCTION

On November 2004 an earthquake hit the area of the lake of Garda, an international tourist area. Though its magnitude was not particularly high (5.2 Richter scale) and fortunately the event did not cause casualties, nevertheless many public and private buildings were damaged. The region is considered as a seismic area and a previous earthquake occurred in 1901.

In the province, around one thousand churches can be found; several were damaged by the earthquake at various levels and in some cases new damage was added to existing defects, due to lack of maintenance. The Dioceses of Brescia decided to provide designs for repair and strengthening of the damaged churches but also for prevention of future damages to all the others too. To this purpose, a preliminary investigation was needed in order to know the state of damage affecting the structures. To L. Binda and her collaborators were assigned the investigation of 10 churches and two rectories. The request was rather peculiar: a quick (within two months) and cheap investigation was needed as a support to the repair project. Architect M. Biasin was the designer and was supported for the struc-

tural analysis by the University of Genoa and Brescia and by some local structural engineers.

The investigation was based on a methodology which was proposed by the authors for the vulnerability study of historic centres in seismic areas. The chosen churches were built in different centuries, show several construction typologies and are representative of the numerous churches of the dioceses. The bearing walls of the churches were all made in stone masonry, frequently two leaf walls with irregular stones and apparently built with different construction techniques. On the contrary, the stones came from local quarries and are rather similar; the same can be said for the mortars.

A preliminary assessment has been made to compare the different results in terms of collapse mechanisms and material properties as requested by the dioceses in order to understand which typology needs more attention for safety and prevention.

2 METHODOLOGY AND LEVEL OF INVESTIGATION

The investigation methodology adopted by the Authors since the beginning of the '90s [Binda et al.; 1999a, Binda et al. 1999b] is based on the principle that knowledge is fundamental for the choice of suitable techniques and materials aimed to the pres-

ervation and damage prevention of the cultural heritage. This methodology has been well calibrated in different on site investigations on historic masonry buildings in the Umbria region after the earthquake of 1997 [Binda et al., 2004a; Cardani, 2004; Binda et al., 2004b] and in the Liguria region [Binda et al., 2003; Anzani et al., 2004]. The earthquake that struck Umbria and Marche regions in '97 gave the occasion to learn that the lack of knowledge on the material and structural behaviour of the existing buildings was, and still is, the main cause of inappropriate choices for the intervention techniques.




Figure 1. Construction phases of the church of S. Michele Arcangelo at Sabbio Chiese.

When dealing with monumental buildings like churches, a detailed investigation is needed in order to accomplish both the conservation demands due to their historic-artistic value, and the safety requirements connected with their public function. The past experience in seismic areas showed that this type of buildings is subjected to typical and repetitive damage mechanisms as: the out of plane rotation of the

façade, the in plane damages of the lateral walls, the damage of the apse and of the bell tower, etc [Dogliani et al., 1994].

As a first step to provide a design for repair and preservation of the damaged churches a preliminary in-situ survey was considered useful to obtain details on the geometry of the structure, identifying irregularities (vertical deviations, rotations, etc.) and to single out the parts where more accurate investigations was needed. The building may have been subjected to the addition of several volumes in different times, and the possible discontinuities between the different volumes could affect the overall seismic behaviour. Therefore, for a reliable interpretation of the signs of damage, the geometrical survey is not enough but also the historical evolution of the structure in its complexity has to be investigated (Figure 1).

Based on the methodology proposed by the authors for the assessment of historic centres [Bosiljkov et al., 2004], the investigation consisted of the following steps: (i) geometrical survey of the building and survey of the crack pattern, (ii) interpretation of the crack pattern and definition of the damage or collapse mechanisms affecting each building, (iii) detection of the connections wall to wall and roof and vaults to walls, (iv) detection of the tension values for steel tie rods, (v) non destructive evaluation of damage, (vi) masonry characterization through the procedure described below and including survey of the masonry texture and of the morphology of the wall sections, on site characterisation of the masonry walls through sonic and flat-jack tests, sampling and characterisation of mortars, plasters and stones in laboratory through chemical, physical and mechanical tests.

It was also important for the authorities to distinguish between damage caused by the earthquake and damage of a different nature which could have been caused by excessive dead load or soil settlements, or simply by lack of maintenance.

2.1 Typology of the buildings and observed damage

Apart from the church of S.S. Crocifisso at Bogliaco di Gargnano, that was built in the 18th cent. and presents a central plane, and from S. Andrea Monumentale at Toscolano Maderno that was founded in Romanic style in 12th century, most of the churches surveyed during the research here described were built between 15th and 17th century and are characterized by a “basilica” plan. Generally they are organized in a unique nave, whereas only S. Pier d’Agrino and S. Andrea Monumentale are based on three naves, with no transept except from S. Antonio Abate at Morgnaga.




Figure 2a. S.S. Crocifisso at Bogliaco di Gargnano: central plane.




Figure 2b. Immacolata at Toscolano Maderno: one nave and no chapels.




Figure 2c. S. Pier d'Agrino at Bogliaco di Gargnano: three naves and chapels.

Some of them have been provided with lateral chapels that are original or have been added according to the *Instructiones* given by C. Borromeo on 1580 to the Milan diocese. In many cases they rise on the place of a previous construction and often have been subjected to later interventions for decoration or strengthening purposes. The churches studied are not isolated buildings, but they generally are annexed to the sacristy, the bell-tower and in some case the rectory. Figure 2a, 2b, 2c show some typical plans.

2.2 Collapse mechanisms

The interpretation of the crack patterns observed on the churches tried first of all to distinguish between the damage caused by the earthquake and that previously present on the constructions for other reasons. Considering the former, some of the mecha-

nisms, for instance those involving the lateral naves, the chapels or the transept, were only relevant to single churches according to the building typology, since these elements are not always present. Other failure mechanisms, like the out of plane rotation of the façade and the hammering action of the roof structure on the lateral walls have only been observed in a couple of cases, probably because of the good connection between orthogonal parts. In the following, only the most diffused collapse mechanisms will be illustrated.

In plane mechanism of the façade

This mechanism has been observed in six cases; it is the most frequent one and always involves simple façades, i.e. plane front only connected to the lateral bearing walls. In all the studied cases, the crack pattern has developed along few well defined lines, indicating a good quality of the masonry 8, 9. The crack position is obviously influenced by the openings too. In figure 3 the church of S. Antonio Abate at Morgnaga is presented: on the central part of the façade a series of cracks are visible corresponding to the windows.




Figure 3. S. Antonio at Morgnaga.



In figure 4 the Church of SS. Crocifisso at Bogliaco di Gargnano can be seen: from the photograph a failure line basically vertical and in central position can be noticed. The cracks are probably generated by the out of plane displacement of the lateral walls and are exacerbated by the presence of the openings.

Failure of the triumphal arch

Because of the out of plane confinement on both sides, the triumphal arches only showed in plane failure that has been detected in four cases. In Figure 5 the triumphal arch of the church of S. Giovanni Pavone at Sabbio Chiese shows a particularly evident crack pattern that required supporting structures. A similar problem is evident in Figure 6 at the arch of the apse, where the movement of the key-stone also required the use of props.




Figure 4. SS. Crocifisso at Bogliaco.




Figure 7. S. Pier d'Agrino, Bogliaco di Gargnano.




Figure 5. S. Giovanni Pavone, Sabbio Chiese; triumphal arch.




Figure 8. S. Benedetto at Pompegnino di Vobarno.



Figure 6. S. Giovanni Pavone, Sabbio Chiese; arch of the apse.

Behavior of the vaults of the central nave

In four cases the vaults of the central nave looked cracked, often due to the heavy load of the re-built roof (Figure 7).

In the case of S. Benedetto da Norcia at Pompegnino di Vobarno (Figure 8) the central nave looks severely cracked, probably because of the presence of a rigid plaster that makes the cracks more evident. The structure has been completely propped to guarantee safety.

Mechanism of the apse

Four churches are affected by the rotation mechanism of the ending part of the apse. In Figures 9, 10 the church of S. Michele Arcangelo at Sabbio Chiese is illustrated. Two long cracks can be seen in symmetrical position, sometimes cutting the whole wall thickness, indicating a detachment of the ending part of the apse due to out of plane rotation.

In plane mechanism of the lateral bearing walls

Because of the good transversal connection offered by the roofs and by the lateral chapels when present, no out of plane rotation of the lateral bearing walls has been observed, except that in the case of the central plane church of SS. Crocifisso, where the vertical cracks in the façade is presumably due to a rotation of the lateral walls. On the contrary, shear cracks showed in the case of three churches. The phenomenon is less frequent than the in-plane mechanism of the façade, probably because of the higher in-plane flexural stiffness of the lateral walls and to the higher slenderness of the façade. In Figure 11 the crack patterns appeared on the north and south walls of the church of S. Antonio Abate at Morgnaga are shown.







Figure 9. S. Michele Arcangelo at Sabbio Chiese.

Figure 10. S. Michele Arcangelo at Sabbio Chiese, apse rotation.

Failure mechanisms of the bell-tower

The bell-tower was not present in all the case studies. In general its failure mechanisms are influenced by its position with respect to the church and by the kind of connections, considering that it may be particularly vulnerable because of its slenderness. In Figures 12, 13 the bell-tower of S. Michele Arcangelo, at Sabbio Chiese is shown, which is affected by severe crack patterns. In particular, the cracks on the east and west fronts indicate a movement of the tower in the north-south direction. In fact, the upper part of the tower can freely move whereas the lower part is well constrained by the church and the rectory. East and west faces of the belfry show a crack corresponding to the keystone, probably due to an out of plane rotation of north and south walls.

3 DAMAGE SURVEY BY NDT

According to the low budget allocated by the single churches, only a few flat-jack and sonic tests were carried out after a very accurate choice of the test positions and some ultrasonic tests for detecting the columns integrity (Figure 14). Systematically, the testing points were chosen in the most representative parts of the bearing walls: taking into account that the façade is usually made of better masonry, the lateral bearing walls were chosen.




Figure 11. S. Antonio Abate at Morgnaga.

The tests were carried out mainly on the outer face of the wall, since the inner one was usually decorated with frescos and paintings which could not be damaged. Dynamic tests on tie rods were also carried out in order to detect the level of tension.




Figure 12. Bell-tower of S. Michele Arcangelo, Sabbio Chiese.





Figure 13. Belfry of S. Michele Arcangelo at Sabbio Chiese.

4 A METHODOLOGY FOR MASONRY CHARACTERIZATION

A complete characterization of the wall was achieved following four subsequent steps in the same area (Figures 17 – 27): (i) sonic tests by transparency on a grid of 75x75cm for measurement of the sonic velocity, (ii) single and double flat-jack tests for measurement of the state of stress, the modulus of elasticity and the coefficient of lateral

expansion, (iii) survey of the masonry morphology and material sampling for characterizing the mortar and stones chemical, physical and mechanical properties, (iv) repositioning of the stones in the wall.




Figure 14. Ultrasonic tests to characterize the inner crack development into a column.

The calculated values of the modulus of elasticity allows to recognize three intervals corresponding to different categories of buildings: 1) from 189 to 803 N/mm² corresponding to a very weak masonry with internal voids and no connection between the masonry leaves, 2) from 1063 to 1732 N/mm², corresponding to a better masonry but with poor connections between the leaves, 3) from 2860 to 5260 N/mm² a definitely compact masonry well connected transversally. Figures 16 - 23 show some typical diagrams obtained with the double flat-jack tests compared with the results of sonic tests where the previous categories can be recognised. In particular, Figure 17 shows a bilinear response with low stiffness, according to a distribution of sonic velocities around very low values (Figure 16). The results have been obtained on the Rectory, which was built with a lower quality masonry than the church, described below. As appears from Figure 15, the masonry is

constituted by roundish stones, many of which of small dimensions, with big amounts of mortar.




Figure 15. S. Antonio in Morgnaga, rectory: redraw of the masonry in the testing area.




Figure 16. S. Antonio in Morgnaga, rectory:sonic tests.




Figure 17. S. Antonio in Morgnaga, rectory: results of flat jack tests.

Figure 20 obtained on the church is typical of medium stiffness masonry, confirmed by an intermediate distribution of sonic values (Figure 19). The masonry aspect, as appears from Figure 18, is characterized by the presence of stones of bigger and more uniform dimensions, though the mortar joints are still rather thick and not precisely horizontal.

Figure 23 obtained on an other church shows higher stiffness of the masonry, also very high values of sonic velocity (Figure 22) and a masonry aspect (Figure 21) characterized by the presence of big stones, with voids filled with stone pebbles and thinner mortar joints. Figure 24 shows the relationship between the sonic velocity and the modulus of elas-

ticity measured by double flat jack tests, compared to other values previously obtained from tests on different stone-masonry walls in historic centers.




Figure 18. S. Antonio in Morgnaga, church: redraw of the masonry in the testing area.




Figure 19. S. Antonio in Morgnaga, church: results of sonic tests.




Figure 20. S. Antonio in Morgnaga, church: results of flat jack tests.

Despite some scatter in the results, obviously due to the non-homogeneity of the masonry studied, nevertheless an interesting direct relationship can be observed.

The survey of the morphology of the wall cross section was aimed to understanding whether the masonry was made of one or more leaves and whether the leaves were connected in some way [Binda et al., 2000, Binda & Tiraboschi, 1999, Saisi et al., 2001].

It was carried out by drilling and taking off some stones in order to visually investigate the wall texture, sketch the inner aspect of the wall (Figure 25), and sample stones and mortars for laboratory testing.




Figure 21. S. Michele in Sabbio Chiese, church: redraw of the masonry in the testing area.




Figure 22. S. Michele in Sabbio Chiese, church: results of sonic tests.




Figure 23. S. Michele in Sabbio Chiese, church: results of flat jack tests.




Figure 24. E vs. sonic velocity.




Figure 25. Study of the masonry morphology.

The mortars were submitted to chemical and physical analyses. The binder was separated from the aggregate by thermal attack and the grain size distribution was calculated as shown in Figure 26. Since the aggregate was mainly calcareous, it was

not possible to determine the binder/aggregate ratio chemically. Figure 27 shows the results of the chemical analyses: most of the mortars were similar, with the binder being hydrated lime.




Figure 26. Grain size distribution of the tested mortar.




Figure 27. Results of chemical analysis on mortars.

Table 1. Physical-mechanical properties of stones: bulk density (d_b), compressive strength (σ_c), indirect tensile strength (σ_t).

Church	Litho type	d_b Kg/m ³	σ_c N/mm ²	σ_t N/mm ²
S. Antonio	Microcr. limestone	2675	103.78	11.82
S. Benedetto		2486.71	87.3	10.3
Immacolata		2684.62	154	11.02
S. Andrea	Sacchar. limestone	2593	171.8	8.8
S. Giovanni		2641	98.2	5.7
S. Martino	Porphyrite	2679.69	12.33	7.12
S. Michele		2495	9.99	7.44
Immacolata	Marly limestone	2659	295	17.31
S. Andrea		2569	116	7.1
S. Crocifisso		2687.84	125	14.90
S. Giovanni	Dolomite	2597	110.6	6.5
S. Pier d' Agrino	Limestone	2583	93.1	7.3
S. Pier d' Agrino	Pure limestone	2351.98	7.30	4.70

The stones belonged to several litho types but limestone was the most frequent one. In Table 1 the results of physical and mechanical tests are reported.

5 DISCUSSION OF THE RESULTS AND CONCLUSIONS

After the investigation here described, the following considerations can be done: according to the church typology, mainly characterized by a unique nave, the most commonly observed failure mechanism is the in plane mechanism of the façade, with a crack pattern influenced by the opening position.

Cracks on the vaults of the central nave mainly occurred due to the heavy load of the re-built roof. Because of the good transversal connection offered by the roofs and by the lateral chapels when present, no out of plane rotation of the lateral bearing walls has been observed, whereas shear cracks showed in some case.

In a few cases, the out of plane rotation of the façade took place, probably because of the low masonry quality and the bad connection between orthogonal walls.

The failure mechanisms of the bell tower, when present, are generally influenced by its position and connections toward the church, being also particularly vulnerable because of its slenderness.

Sonic tests, flat jack, small disassembling and laboratory tests in sequence are essential to characterize the masonry typology and mechanical behaviour and the masonry material. The survey of the wall section is also useful to detect the masonry injectability, for repair by grout injection.

ACKNOWLEDGEMENTS

The authors wish to thank Informazioni Mb Studio S.r.l., directed by M. Biasin and the parish priests who supported the experimental investigation. The research was co-financed by the National projects RELUIS. M. Antico, M. Cucchi, M. Iscandri, G. Rossi and C. Schiaffi are gratefully acknowledged for their technical support; many thanks are also due to the students: L. Bianchi, C. Danieli, M. De Bernardi, O. Gabbiadini, D. Metallo D. Mori, F. Perlini, F. Pianezze, M. Oprandi, S. Seveso, V. Sgobba.

REFERENCES

- Anzani A., Baila A., Penazzi D., Binda L., 2004, Vulnerability study in seismic areas: the role of on-site and archives investigation, *IV Int. Seminar Structural Analysis of Historical Constructions*, Padova 10-12/11/2004, Vol. 2, pp. 1051-1059, ISBN 04 15363799.
- Binda L., Baronio G., Gambarotta L., Lagomarsino S., Modena C., 1999a, Masonry constructions in seismic areas of central Italy: a multi-level approach to conservation, *8NAMC (North American Masonry Conf.)*, Austin, USA, pp. 44-55, CD-ROM.
- Binda L., Palma M., Penazzi D., 1999b, Cautious repair of stone-masonry structures in seismic areas, *Internationale Tagung Conf. on Arbeitshette des SFB 315*, Karlsruhe, pp. 99-108.
- Binda, L., Tiraboschi C., 1999c, Flat-Jack Test as a Slightly Destructive Technique for the Diagnosis of Brick and Stone Masonry Structures, *Int. Journal for Restoration of Buildings and Monuments, Int. Zeitschrift für Bauinstandsetzen und Baudenkmalpflege*, Zurich.
- Binda L., Saisi A., Tiraboschi C., 2000, Investigation procedures for the diagnosis of historic masonries, *Construction and Building Materials*, Vol.14, pp. 199-233.
- Binda L., Anzani A., Baila A., Baronio G., 2003, A Multi-level Approach for Damage Prevention in Seismic Areas. Application to Historic Centres of the Western Liguria, in *The Masonry Society, Proceedings of the Ninth North American Masonry Conference*, Omnipress, Madison, Wisconsin, ISBN 1-929081-16-2, pp. 556-566.
- Binda, L., Cardani, G., Saisi, A., Modena, C., Valluzzi, M.R., Marchetti, L., 2004a, Guidelines for Restoration and Improvement of Historical Centers in Seismic Regions: the Umbria Experience, *IV Int. Seminar, Structural Analysis of Historical Constructions*, Padova 10-12/11/2004, Vol. 2, pp. 1061-1068, ISBN 04 15363799.
- Binda, L., Cardani, G., Saisi, A., Modena, C., Valluzzi, M.R., 2004b, Multilevel Approach to the Analysis of the Historical Buildings: Application to Four Centers in Seismic Area Finalised to the Evaluation of the Repair and Strengthening Techniques, *Proc.13th International Brick/Block Masonry Conference*, RAI Amsterdam, the Netherlands, CD-ROM.
- Bosiljkov V., Tomazevic M., Binda L., Tedeschi C., Saisi A., Zanzi L., da Porto F., Modena C., Valluzzi M.R., 2004, Combined In-situ tests for the Assessment of Historic Masonry Structures in Seismic Regions, *IV Int. Seminar Structural Analysis of Historical Constructions*, Padova 10-12/11/2004, Vol. 1, pp. 321-329, ISBN 04 15363799.
- Cardani, G., 2004, *La vulnerabilità sismica dei centri storici: il caso di Campi Alto di Norcia. Linee guida per la diagnosi finalizzata alla scelta delle tecniche di intervento per la prevenzione dei danni*, Ph.D. thesis, Politecnico di Milano, Italy.
- Dogliani, F., Moretti, A., Petrini, V. (ed. by), 1994, *Le chiese e il terremoto*, Edizioni LINT, Trieste.
- Saisi A., Valle S., Zanzi L., Binda L., 2001, Radar and Sonic as Complementary and/or Alternative Tests in the Survey of Structures, *Int. Congr. More than Two Thousand Years in the History of Architecture Safeguarding the Structure of our Architectural Heritage*, Bethlehem, (Palestine), Vol. 1, Section 1b, pp. 1-6.