




22. STRUCTURAL UNIT nr. 12					
22.1 ANALYSIS of the STRUCTURAL UNIT	Is the structural unit labile?		YES	NO	
			x		
THIS STRUCTURE IS LABILE: IT IS NECESSARY TO MODIFY THE RAFTER-POST- STRAINING BEAM CONNECTION IN ORDER TO AVOID LABILITY.					
22.2 ANALYSIS of STRUCTURAL ELEMENTS   	22.2.1 Rafter		int.	ext.	
	Cross section	round			
		rectangular	x	x	
		other:			
	Dimension (wxd): 18x20 cm				
	Decay:				
	22.2.2 Tie beam				
	Cross section	round			
		rectangular		x	
		other:			
	Dimension (wxd): 25x25 cm				
	Decay:				
22.2.3 Straining beam					
Cross section	round				
	rectangular		x		
	other:				
Dimension (wxd): 25x25 cm					
Decay:					
22.2.4 Queen Post	nr. 2		int.	ext.	
Cross section	round				
	rectangular	x	x		
	other:				
Dimension (wxd): 20x20 cm					
Decay:					
22.3 ANALYSIS of the JOINT	FOOT JOINT		int.	ext.	
	22.3.1 Rafter - Tie beam	Single step joint		x	x
		Double step joint			
		Reverse step joint			
			notch depth:	Few centimeters. External connection could not be inspected.	
		Tenon and mortise			
		Angle: ~ 23°			
		Decay:			
		Fasteners: heel straps, bolts...			
		other:			
		22.3.2 Tie beam - Wall plate	Halving joint		
	Dovetail joint				
Simply supported				x	
Decay:					
Fasteners: heel strap, bolts...					

Figure 1. Guided survey form for vulnerability assessment, software version.



Figure 2. Queen-post truss with potentially unstable layout.




Figure 3. Connections between king-post structures.



Figure 4. Irregular cross section of the rafter .



Figure 5. Biotic decay due to insects.



Figure 6. Wedges adopted to recover contact at the rafter (right rafter and purlin).

For personal use only

For personal use only




Figure 7 (a) Rafter-tie beam joint. Connection reinforced with metal heel straps. The head of the tie-beam is built-in and cannot be inspected; (b) Different types of joint reinforcements and vulnerability class (modified from Parisi and Piazza 2002).



Figure 8 - Collapse due to massive intervention substituting timber trusses with concrete products at Amatrice, Central Italy earthquake, 2016.




Figure 9. The roof structure analysed: (a) internal view (b) numerical model with main elements



Figure 10. Detail of the roof structure.

1 Introduction

2 Methods for assessing the seismic vulnerability of buildings within risk mitigation programs were
3 first developed in the 1980's, after the occurrence of devastating earthquakes in Europe (e.g.
4 Friuli, 1976, and Irpinia, 1980, in Italy; Vrancea, 1977, in Rumania). Vulnerability studies aimed
5 at sorting out the most significant features that condition the building response and at
6 developing rapid assessment procedures to be applied to a building stock for a first screening of
7 critical cases. Initially, evaluation criteria and practical assessment procedures were developed
8 for residential masonry buildings, which were responsible for a large part of the seismic risk
9 (e.g. Benedetti and Petrini, 1984; Sandi, 1986; Petrovski et al., 1985); later, other typologies
10 have been considered, including cultural heritage assets such as churches and palaces (e.g.
11 Lagomarsino and Podestà, 2004a, 2004b).

12
13 Studies and applications of vulnerability concepts have continued to date. In Italy, the recent
14 public campaign for supporting the seismic improvement of the building stock with partial public
15 funding opens new perspectives for vulnerability assessment and needs to be supported by a
16 suitable framework at various accuracy levels. This is a strong motivation for reconsidering and
17 renovating paradigms on which assessment has been based so far.

18
19 An important part of vulnerability studies concerns elements that are not strictly part of the
20 building structure, yet may affect its response. The roof structures, which in traditional buildings
21 are usually assemblies of timber trusses, have shown strong influence on the building
22 behaviour. In a seismic event, a favourable outcome may depend on the capability of the roof
23 structure to connect walls enhancing their collaboration, rather than impinge on them and trigger
24 their failure.

25
26 In the assessment procedures for different construction typologies, consideration of the roof
27 influence has been very synthetic, and often somewhat superficial, lacking a thorough exam of
28 the roof structure and of its possible interaction with the wall system. Various factors contribute
29 to the vulnerability of a roof structure and should be considered in the assessment. Here, the
30 principal ones are examined and grading criteria are given, in order to supply a general
31 framework for evaluating roof structures per se and in relation to the whole building.

32
33 The detail in which a vulnerability assessment may be conducted depends on the final objective
34 and in part also on external circumstances, usually related to the possibility of actually
35 performing a visual analysis more or less in depth. The assessment, for instance, may be
36 performed:

- 37 – within a global assessment of a building;
- 38 – specifically for the roof structures to decide needs and priorities of intervention;
- 39 – to gather information on a specific roof structure as part of a database collection for
40 listed cultural heritage assets;
- 41 – prior to planned restoration interventions, in order to shed light particularly on the
42 expected seismic behaviour, which requires considering specific construction
43 characteristics.

44 Each objective implies a different depth of investigation. The criteria and indications expressed
45 in the following constitute a general basis, in view of formulating assessment procedures at
46 different levels of detail. One such procedure, intended for the second case listed above, has
47 been developed by the authors and is presented here.

48
49 The need to formalize specific criteria for the evaluation of timber roof structures stems not only
50 from their constructional characteristics, governed by peculiar mechanical and physical
51 properties, but especially from the fact that such structures were mostly built with reference to
52 vertical loads, including the effect of wind that for common pent inclinations results in an almost
53 vertical pressure or suction. Earthquakes activate structures mainly in the horizontal direction.

54
55 A standardized assessment procedure allows a more homogeneous and coherent evaluation
56 among different cases as well as among different survey teams. Assessments may be
57 advantageously supported by the use of pre-organized templates implemented on paper forms
58 or with software systems. The former are a common choice for surveys, the latter allow an
59 efficient organization of collected data and may provide more efficient guidance to the

60 evaluation of the different features related to vulnerability. Some characteristics desirable in a
61 system are outlined in the following, making reference to a developed prototype.

62 63 **2. Damage and vulnerability in timber roof structures**

64 Post-earthquake damage surveys have been the major source of information on the seismic
65 behaviour of buildings and other structures. The difficulty of reaching roof structures in a
66 seriously damaged building, especially in the presence of large amounts of debris, and the final
67 state of a collapsed roof, which may suffer complete destruction because of brittleness of the
68 material, may not allow to reconstruct reliably the failure path. Moreover, the minor importance
69 that is traditionally attributed to these structures, always seen as secondary and temporary,
70 leads to focus attention on other parts of a damaged building. Consequently, roof damage data
71 have not been collected systematically. Some indications about vulnerability derive from known
72 construction characteristics and material properties. A useful source of knowledge is scientific
73 literature, with studies on structural identification of existing roof structures (e.g. Faggiano et al.
74 2018a, 2018b) and failure analysis (Tampone, 2016).

75
76 The possibility for the structure to resist shaking with little or no damage depends on:

- 77 - its structural scheme, a determinant issue for structures not specifically built for
- 78 horizontal loads;
- 79 - the capacity of the cross sections to absorb safely the increase of internal actions that
- 80 may result from the earthquake.

81 The structural typology and the member dimensions are, thus, important contributors in the
82 vulnerability definition.

83
84 Connection of timber elements was traditionally performed with carpentry joints that skilfully
85 transmit loads by direct contact. Often, they were supplemented with metal devices acting as a
86 safety measure toward exceptional actions that may disconnect the assembly. Joints are a
87 discriminating element in terms of suitable response. Their diversity and their correct realisation
88 may condition significantly the structural behaviour. Joints are, then, another factor that qualifies
89 vulnerability.

90
91 A frequent cause of severe damage is the loss of support, when the roof structure separates
92 from the wall, sliding off and often engaging the structures below, slabs or vaults, in a
93 progressive collapse. Therefore, a primary source of vulnerability resides in the design and
94 quality of the supports.

95
96 Timber properties are highly susceptible to different conditions of environmental and biological
97 origin. Additional alterations may derive from human action, for instance modifications
98 performed in the lifespan of the structure. The current state of the structure, in its many folds, is
99 another determining factor to be considered.

100
101 A vulnerability assessment procedure will necessarily comprise the exam and evaluation of
102 these issues, to an extent that depends on the accuracy level required.

103
104 Wood characterization is usually of top importance. Although the determination of the species
105 remains a step to be performed within general assessment procedures, it is not considered a
106 primary factor in seismic vulnerability. It is an indirect one, affecting other issues like cross
107 section adequacy or the behaviour in adverse climate conditions.

108 109 **3. Definition of an assessment procedure**

110 Vulnerability assessment requires both a thorough visual and instrumental analysis and an
111 elaboration of the observations according to predefined criteria, making use of evaluation scales
112 for classifying parameters, features, and conditions concerned.

113
114 Visual analysis is the first step to be performed and it is critical for creating the appropriate
115 basis, in terms of data and information, for the subsequent assessment phase.

116
117 Survey sites are often in precarious environmental conditions, with great amounts of trash, dust
118 and droppings, subdued light, and difficulty of access: a state that may hinder regular

119 operations. For this reason, a prescribed scheme for the operations to be performed should be
120 used to avoid excessive emphasis on some aspects or disregard of others, ensuring a coherent
121 and well balanced survey. A paper form with the sequence of items to be observed and data to
122 be collected has been developed and subsequently implemented in a software version (Parisi et
123 al., 2008, 2017) (Figure 1).

124 During inspection, all data and general impressions are collected (Cruz et al. 2015, Feio and
125 Machado 2015, Kasal and Anthony 2004, Kasal and Tannert 2010). The proper vulnerability
126 analysis is performed in a second step, because it requires to interpret the collected data with a
127 global vision, evaluating those issues that have been recognized as significant indicators of the
128 capability of seismic response, or vulnerability indicators.

129 In summary, the procedure amounts to:

- 130 - first step, on site: guided survey;
- 131 - second step, off-site: vulnerability analysis and classification.

132

133 According to section 2, a comprehensive assessment should investigate:

- 134 - the conceptual design and its realisation;
- 135 - the quality of connections;
- 136 - the retaining system, or roof-wall interface;
- 137 - the current state of the structure.

138 These points correspond to the indicators considered in the procedure.

139 Each of these items may be further subdivided pointing out different issues to be examined. The
140 following sections offer a detailed description and reference criteria for each.

141

142 A fundamental question is the choice of a reference scale for grading and comparing the levels
143 of vulnerability. Different choices may apply, depending also on the purpose of the survey,
144 ranging from a yes/no outcome for a rapid decision in emergency, to a global numerical index,
145 which allows to develop statistics from large scale surveys. An intermediate choice, adopted
146 here, is to express grades with a linguistic variable. They may be subsequently transposed into
147 a numerical value, after suitable calibration. Grading criteria are:

- 148 - Grades range from A to D through B and C;
- 149 - The value A corresponds to the minimum vulnerability of a structure designed, executed
150 and maintained according to best practice, incorporating all the positive features in
151 favour of seismic safety, comparable to a new code-designed structure;
- 152 - D corresponds to the highest vulnerability level, that is, a structure with serious
153 deficiencies that should be promptly reduced by suitable interventions;
- 154 - B and C represent intermediate levels: B denotes situations not fully satisfactory but not
155 requiring action in a short time; C indicates criticalities apt to evolve into negative
156 consequences, for which an improvement should be considered.

157 This scale may be applied to the four indicators above, and to the different issues, or partial
158 indicators, considered within them. Grading references and examples are in sections 5 to 8.
159 Grades highlight the criticalities of the structure and give a measure of their severity. Their
160 plurality supplies a global picture of the seismic quality of the system. If a global index for the
161 structure is needed, different ways of combining partial results may be proposed. These are
162 commented in section 9.

163

164 **4. The survey**

165 A direct survey carried out simply by visual inspection or with the support of diagnostic tests and
166 instruments is the kernel of any assessment procedure for timber roof structures (Dietsch and
167 Koehler 2010, Riggio et al. 2014).

168

169 Before any other issue, a safe access to the structure must be guaranteed (UNI 11119:2004),
170 with a safety check of the actual capacity of the elements to be accessed by inspecting
171 personnel. It detects insufficient cross sections and the presence of decay by fungi, often
172 indicated by wood colouring, which may abate the load bearing capacity.

173 Often, only a limited access is possible, so the extension of the survey should be indicated in
174 the survey form.

175

176 In the spirit of a seismic vulnerability assessment, only simple, indispensable instruments are
177 used. Besides tools to improve vision in dim light conditions, basic implements are measuring

178 tapes and laser distance-meters to trace horizontal and vertical alignments, a camera to record
179 images, a hammer and possibly a hygrometer. When more sophisticated exams are required, a
180 Resistograph and similar devices are needed, considering that a comparison among tests of
181 different type offers a general and more complete vision (Piazza and Riggio, 2008).

182
183 In order to organize the collected information, a reference system permitting to identify all the
184 members with progressive numbering must be defined and reported in the form. For instance,
185 for a roof structure covering a church, the direction along and across the nave would constitute
186 a reference, as well as the left and right-hand-side with respect to the nave axis.

187
188 The first action is the characterization of the environment in terms of temperature and humidity:
189 even though no continuous measures are usually taken, excessive values at survey time
190 indicate risk of decay. As a reference, to avoid fungi growth, humidity must remain below 80-
191 90%, a rather high value. Yet, the presence of water cumulated on surfaces and in cracks may
192 generate the problem.

193
194 The subsequent steps in the survey procedure examine the different elements of the structure
195 related to the indicators.

196 **5 Elements for structural typology analysis**

197 **5.1 The layout**

198 Examining the structural scheme, the first element to be considered is the basic structural unit
199 and its connection to other units to form a three-dimensional roof structure. Good seismic
200 performance is possible when stiffness and resistance are equally distributed in the main
201 orthogonal directions: the degree of three-dimensionality is inversely related to vulnerability.
202 In common construction, roof structures are seldom conceived as fully three-dimensional.
203 Usually, a series of parallel trusses are transversally interconnected to form a spatial system.

204
205 Instabilities in the structural scheme, usually due to insufficient joint constraints, are identified
206 first. They occur mainly in double-level, queen-post trusses (figure 2), with details probably
207 inspired by examples in classic architectural treatises, which have influenced constructional
208 practice contributing to their diffusion (e.g. Palladio A, 1570). It is worth noting that joints need to
209 be observed accurately to establish the kind and level of constraint they may offer. Insufficiently
210 constrained structures may be capable of supporting symmetrical vertical loads, resorting also
211 to some joint semi-rigidity to respond to minor load deviations. The resisting system, however, is
212 not adequate for asymmetrical vertical loads or for the horizontal forces generated by seismic
213 action. This condition will correspond to a D.

214
215 Transversal secondary trusses supply good connectivity, classified with A. (Chesi et al. 2012).
216 Often, the connection between trusses is simpler, with purlins and a ridge plate as in figure 3,
217 sometimes with the addition of transversal struts, or diagonal bracings (Parisi et al. 2016). The
218 most common situation presents two purlins per rafter, which may give satisfactory results if
219 purlins and rafter are well connected: it would be graded up to A in the best conditions.
220 Intermediate situations, mainly related to quality of connection, purlins cross section and
221 regularity, are more difficult to grade and will range between B and C. When only one purlin per
222 rafter is present, or more purlins with insufficient connection, the assembly is deemed too
223 deformable in the transversal direction (C to D).

224
225 In the survey form, only the most frequent truss types are currently considered: coupled rafters,
226 couples closed with a tie-beam, simple-post trusses, king-post trusses with struts, and double
227 level queen-post trusses in various shapes. The truss type is usually related to the span it has
228 to cover. Traditionally, up to 6-7 m, closed couple roofs are found; for higher spans, up to about
229 15 m, a king-post truss with struts is normally adopted; longer spans, up to 25-30 m, often
230 covering public halls, usually require more elaborated systems, like a two-level, queen-post
231 truss. A previous study comprising dynamic analyses of a large series of trusses differing in
232 type, span, members size, quality and stiffness of joints, has shown that the empirical sizing
233 rules of the constructional tradition combine correctly span lengths, minimum cross section
234 sizes and structural layout also with respect to dynamic response (Chesi et al, 2012). For
235 trusses of common size, the study identified three classes of vulnerability, A, B, C, associated to
236 the values of the main design parameters. Classes can be assigned on the basis of geometric

237 dimensions, observable by direct inspection. Table 1 offers guidance, reporting grades for truss
 238 schemes compatible with the span length. Trusses with under-dimensioned sections and errors
 239 in the conceptual design are classified as D.

240
 241 Table 1 – Grade examples for structural typology

Three-dimensionality		Dimensions and type					
Structural scheme		Cross-Section [cm×cm]	Span [m]				
Trusses in orthogonal directions	A		6	9	12	18	24
Parallel trusses with transversal bracings or struts	A-B	15×15	A	B	C		
Parallel trusses with at least 2 purlins per rafter	A-B	20×20		A	B	C	C
Parallel trusses with 1 purlin per rafter	C-D	25×25			A	B	B
Couple roof (no tie-beam)	C-D	30×30				A	A

242
 243 **5.2 Structural elements**

244 The inspection of structural members estimates their adequacy in supplying the bearing
 245 capacity required for the increased stress level due to seismic action. Focus is on geometry and
 246 material properties. Existing structures often present generously dimensioned cross-sections
 247 that may accommodate such increase, yet specific considerations are due.

248
 249 The strength strictly depends on the mechanical properties of the wood species and moisture
 250 content. In order to perform a correct recognition of wood species experience is needed. The
 251 investigation may be performed either at macroscopic level, recognising typical characteristics,
 252 or by microscopic analysis (Macchioni, 2010). The norm UNI 11118:2004 supplies a useful
 253 guide for wood species identification. Lacking this kind of information and for a rapid
 254 assessment, other factors like documentation of construction, maintenance reports and at least
 255 the species used in the area become a reference. Once the species has been defined, a
 256 corresponding strength and service class for new wood may be examined to obtain indicative
 257 values. The strength of members in an existing structure may be assessed by testing (e.g.
 258 Tannert et al. 2014, Kloiber et al 2015, Riccadonna et al 2019) or by visual grading; when their
 259 inspection is possible at least on three sides and one head, indications from UNI EN 11035-
 260 2:2010 assign a strength class on the basis of the position, number and dimensions of knots,
 261 smooth edges, cracks, slope of grain, and rings size (CEN EN 14081-1:2016). If the inspection
 262 requirements cannot be satisfied, an estimation is possible according to UNI 11119:2004,
 263 which, based on observed data, supplies allowable strength values and average values of
 264 elasticity modulus. Current codes for structural analysis and design (e.g. Eurocode 5:2014) refer
 265 to the use of values for limit states. A useful expression permits to pass from allowable stress to
 266 limit states values (Riggio et al., 2012).

267
 268 Evaluation of the bearing capacity of a structural element requires measuring length and cross
 269 section, detecting possible irregularities along the length, as in figure 4, in order to identify its
 270 minimum cross section area (Lourenço et al 2013, Sousa et al 2014). Only off-site it will then be
 271 possible to define loads, perform structural analysis and check structural adequacy.

272
 273 Wood decay, a major cause of section inadequacy, may be distinguished in biotic decay when
 274 caused by insects and fungi and mechanical degradation caused by excessive stress levels.
 275 Each wood species is more or less prone to biotic attacks (fungi, insects). The EN 350:2016
 276 norm reports detailed references for the resistance of each species and element service class
 277 to borer attacks. Thus, in order to define the effective cross-section, it is necessary to check
 278 biotic factors that may reduce the element size (figure 5). The presence of fungi is strictly
 279 related to the humidity content of wood. Specifically, in timber elements a humidity percentage
 280 of 18-20% or greater constitutes an environment favourable to their development. If humidity is
 281 to be measured, electrical hygrometers operate exploiting the electrical properties of wood (EN

282 13183-2:2003). Their use is rather delicate, because many factors influence measures, from
 283 temperature to characteristics of wood elements, (knots, grain slope). More recent methods
 284 have been adopted, like infrared thermography and microwaves (Riggio et al. 2015), which
 285 along with more traditional ones, may be used also for detecting insects.

286
 287 Mechanical degradation is intended as the damage produced by excessive stress levels. For
 288 an accurate quantification of the residual effective cross section and of the extension and
 289 position of the lesion, different diagnostic tools (Resistograph, Pylodin, etc.), together with
 290 ultrasonic and thermographic tests may be used.

291 Excessive deformations, compared to reference values in design, may be associated to various
 292 causes, including mechanical degradation. The deflection with respect to the undeformed shape
 293 may be measured, possibly with a simple stiff ruler, and compared to the element length.

294 Excessive deformation could derive from a connection that lost effectiveness. Sometimes the
 295 presence of wedges applied in correspondence of a significant deformation indicates an
 296 intervention carried out for remediating a lacking connection (figure 6).

297

298 **6 Traditional carpentry joints**

299 Type, quality and effectiveness may vary strongly in carpentry joints. In seismic conditions, two
 300 features qualify their adequacy:

- 301 – the capability to maintain the assembly during cyclic conditions, when compression
 302 between the joined elements may temporarily decrease;
- 303 – the post-elastic behaviour, with the aim at sorting out possible brittle failure modes.

304 In recent times, considerable research effort has been devoted by different groups to the
 305 characterization of carpentry joints and to the definition of suitable retrofitting interventions (e.g.
 306 Branco et al 2011, 2017; Moşoarcă and Gioncu 2013, Franke et al 2015, Šobra et al 2016).

307 Indications for evaluating adequacy for different types of joints have been derived here mainly
 308 from a research program on their monotonic and cyclic behavior in the elastic and post-elastic
 309 field (Parisi and Piazza, 2000, 2002).

310

311 Traditionally, carpentry joints, which commonly transmit forces by compression and friction,
 312 were equipped with binding strips or other metal devices to avoid accidental loss of contact.

313 This condition may occur under an earthquake. Unrestrained or ineffectively restrained joints
 314 may undergo disassembly; they are at the worse side of the vulnerability scale and are
 315 classified as D. Partial degradation or an imperfect realisation of the connection may be
 316 associated to intermediate vulnerability levels, indicating the need of an improvement.

317 Brittle failure modes are equally to be avoided. Reinforced joints with excessive stiffening, like
 318 metal cages or cuffs that will limit minor movement and deformation are critical. Experimental
 319 testing has shown that risk may derive also from a limited amount of connectors, when they are
 320 positioned in a pattern that prevents or limits rotation (figure 7). Identification of possible sources
 321 of brittleness requires particular care. Sliding shear at the toe of a rafter-to-chord joint in a truss
 322 is another cause of brittle failure. Short toe areas with low rafter and chord skew angle may
 323 result in sliding failure under seismic action, incrementing the vulnerability of the assembly.

324 Table 2 gives guidance for the rafter-to-chord connection and may be a reference for similar
 325 situations.

326

327 Table 2 – Guide for joint assessment

Reinforcement type	class
Unreinforced, no provisions for disconnection	D
Reinforced, with	
1 bolt	B
≥ 2 bolts, small diameter,	
- Permitting minor rotation	A
- Blocking rotation	C
Stirrups	C
Binding strip	
- fixed	B
- adjustable	A
Steel cuff	D

328
 329
 330
 331
 332
 333
 334
 335
 336
 337
 338
 339
 340
 341
 342
 343
 344
 345
 346
 347
 348

7 The supports

At the truss-to-wall interface, the chord extremes may be:
 - supported at the top of the wall, or within a niche;
 - built-in.

The restraint may be assessed by the degrees of freedom that remain unlimited: translation parallel to the tie-beam axis, lateral translation, and rotation of the entire truss around the tie-beam axis, often observed in earthquake damage surveys. The effect of unrestrained or poorly restrained rotation may be counterbalanced by bracings in the longitudinal direction of the roof.

For displacements parallel to the beam axis, tending to drop the truss from the support, examples of good construction techniques may be found, with the beam anchored to the wall base or, according to some constructional tradition, with metal elements nailed to its sides and retained at the wall exterior. When the beam end is enclosed in the wall without possibility of inspection, assessing the extension of the restrained area is impossible and the probability of timber decay due to humidity without ventilation is realistic. The possibility of unseating, and the related vulnerability, must be considered. Table 3 gives tentative grading indications.

Table3 - Classification of supports

Support type	class
No restraint and insufficient extension	D
No restraint, extended support area	C-D
Free rotation without bracings	C
Free rotation, with bracings	A-B
Fixed end, with external restraints, inspectable	A
Fixed end, partially or not inspectable	B-D

349
 350
 351
 352
 353
 354
 355
 356
 357
 358
 359
 360
 361
 362
 363
 364

8 State of the structure: maintenance and interventions

This vulnerability indicator collects different issues, related to the situation of the timber structure. The main ones may be synthetised in the level of maintenance that affects the current quality of the structure, and in the modifications to the original layout performed in its lifetime.

Poor maintenance plays a significant role. The state of the roof cover should be checked, because rainwater entering from gaps will rapidly deteriorate the underlying structure, even if such effect is not yet observable. The assessment itself would soon loose significance. A possible reference for maintenance grading could be A for good state and frequent, preplanned inspections, D for evident serious lack of maintenance and inspections, with B and C intermediate situations from observation and from information on inspection intervals if available (Table 4).

Table 4 – Grade reference for state of the structure

Item	Class range	
maintenance		
	roof cover damage	A none B initial C evident D extended
	general check/ maintenance	A recent/regularly planned B recent/not planned C irregular D none
decay		

	element sections reduction	B-D
	decay of joints	B-D
Previous interventions		
	modification of elements	A (improved), B-D
	With increased loads	C-D

365

366

367

368

369

370

371

372

373

374

375

376

377

378

379

380

381

9. Global evaluation

382

Statistical or risk management reasons may require a global vulnerability measure.

383

384

385

386

387

388

389

390

391

392

393

394

395

396

397

398

399

10. IT extension

400

401

402

403

404

405

406

407

408

409

410

411

11. Vulnerability assessment of a 20th century timber roof structure.

412

413

414

415

416

417

418

The criteria and the assessment procedure have been applied in several cases, also for calibration purposes (e.g. Parisi et al 2010). A recent application concerned the roof structure of a large masonry building, an alpine hotel, dating back to the early 20th century and currently in disuse. The roof structure is composed of 13 trusses with slightly different layout, covering and L-shaped area, according to the scheme of figure 9. Spans range between 7 and 8 m, with spacing between 3.30 and 4.40 m (figure 10). Survey data for structural units, elements and connections have been collected in the relevant forms (e.g in figure 1). The global vulnerability

419 was deemed high, D, because two of the trusses resulted insufficiently restrained to lateral
420 loads (structural typology D). Additionally, a small number of elements had section reductions
421 due to decay, and new metal connectors were needed for most joints to avoid disassembly. A
422 plan of interventions, with their basic design, was proposed to bring the structure to very low
423 vulnerability. A structural analysis carried out in the assumption that interventions had been
424 performed showed full satisfaction of seismic response requirements.

425

426 **12. Conclusions**

427 A long research program on the role of timber roof structures in the seismic behaviour of
428 masonry buildings has highlighted the factors that affect their seismic vulnerability and often that
429 of the entire structural compound. A procedure to assess the seismic vulnerability of roof
430 structures was defined. The procedure, currently suited for structures composed of trusses, will
431 require improvements as well as extension to a larger number of typologies. Still, in applications
432 and case studies performed so far it has proven useful to focus attention on the seismic
433 qualification of these structures, mainly seen, and originally conceived, with regard to vertical
434 loads.

435

436 **Acknowledgements**

437 Financial support by the Reluis-DPC Program is gratefully acknowledged.

438

439 **References**

- 440 Benedetti D and Petrini V (1984) Sulla vulnerabilità sismica degli edifici in muratura: un metodo
441 di valutazione. *L'Industria delle Costruzioni* **149**: 66-74.
- 442 Binda L, Chesi C and Parisi MA (2010) Seismic Damage to Churches: Observations from the
443 L'Aquila, Italy, Earthquake and Considerations on a Case-study, *Advanced Materials*
444 *Research*, pp.641-646 DOI:10.4028 /AMR.133-134.641.
- 445 Branco, J.M., Piazza, M., Cruz, P.J.S. (2011), Experimental evaluation of different strengthening
446 techniques of traditional timber connections. *Engineering Structures*. 33 (8), 2011, 2259-
447 2270. URI: <http://hdl.handle.net/1822/13592>
- 448 Branco JM, Sousa HS, Tsakanika E (2017) Non-destructive assessment, full-scale load-carrying
449 tests and local interventions on two historic timber collar roof trusses, *Engineering*
450 *Structures*, vol. 140, pp. 209-224.
- 451 CEN (2003) EN 13183-2: Moisture Content of a Piece of Sawn Timber – Part 2: Estimation by
452 Electrical Resistance Method. European Committee for Standardization, Brussels.
- 453 CEN (2014) EN 1995-1-1: Eurocode 5 – Design of Timber Structures – Part 1-1: General –
454 Common Rules and Rules for Buildings. European Committee for Standardization, Brussels.
- 455 CEN (2016a) EN 350:2016 Durability of wood and wood-based products. Natural durability of
456 Solid wood. Guide to the principle of testing and classification of the natural durability of
457 wood. European Committee for Standardization, Brussels.
- 458 CEN (2016b) EN 14081-1: Timber Structures – Strength Graded Structural Timber with
459 Rectangular Cross-Section – Part 1: General Requirements. European Committee for
460 Standardization, Brussels.
- 461 Chesi C, Parisi MA and Tardini C (2012) Inferring seismic behavior from morphohology in timber
462 roofs, *International Journal of Architectural Heritage*, vol. 6, pp. 100-116,
463 DOI:10.1080/15583058.2010.511693
- 464 Cruz H, Yeomans D, Tsakanika E et al. (2015) Guidelines for On-Site Assessment of Historic
465 Timber Structures. *International Journal of Architectural Heritage* **9(3)**: 277-289.
466 <https://doi.org/10.1080/15583058.2013.774070>.
- 467 Dietsch P and Koehler J (2010) Assessment of Timber Structures, COST Action E55. Modelling
468 of the Performance of Timber Structures. Shaker Verlag. Herzogenrath.
- 469 Faggiano B, Marzo A and Mazzolani FM (2018a) The Diplomatic Hall of the Royal Palace of
470 Naples: structural identification of the roofing timber structures by ND tests. *Construction and*
471 *Building Materials*, vol. 171, pp1005-1016, doi:10.1016/j.conbuildmat.2015.07.174.
- 472 Faggiano B, Marzo A, Grippa MR, Iovane G, Mazzolani FM and Calicchio D (2018b) The
473 inventory of structural typologies of timber floor slabs and roofs in the monumental built
474 heritage: the case of the Royal Palace of Naples. *International Journal of Architectural*
475 *Heritage*, vol. 18(4). doi:10.1080/15583058.2018.1442525.

476 Feio A and Machado JS (2015) In-situ assessment of timber structural members: combining
477 information from visual strength grading and NDT/SDT methods. A review. *Construction and*
478 *Building Materials* 101(2): 1157-1165. <https://doi.org/10.1016/j.conbuildmat.2015.05.123>.

479 Franke S, Franke B, Harte AM (2015) Failure modes and reinforcement techniques for timber
480 beams – State of the art, *Construction and Building Materials*, Volume 97, pp 2-13,
481 <https://doi.org/10.1016/j.conbuildmat.2015.06.021>

482 Kasal B and Tannert T (2010) *In Situ Assessment of Structural Timber*. RILEM State of the Art
483 Reports. Springer. Netherlands.

484 Kasal B and Anthony RW (2004) Advances in in situ evaluation of timber structures. *Progress in*
485 *Structural Engineering and Materials* 6: 94-103. doi: 10.1002/pse.170.

486 Kloiber M., Drdácý M., Machado J.S., Piazza M., Yamaguchi N., (2015) Prediction of
487 mechanical properties by means of semi-destructive methods: A review, *Construction and*
488 *Building Materials* 101 1215–1234 (on line DOI: 10.1016/j.conbuildmat.2015.05.134)

489 Lagomarsino, S., Podestà, S.(2004a). Seismic vulnerability of ancient churches: part 1. Damage
490 assessment and emergency planning, *Earthquake Spectra*, 20(2), pp.377-394.

491 Lagomarsino S and Podestà S (2004b) Seismic vulnerability of ancient churches: II. Statistical
492 Analysis of Surveyed Data and Methods for Risk Analysis. *Earthquake Spectra* 20(2): 395-
493 412. <https://doi.org/10.1193/1.1737736>.

494 Lourenço PB, Sousa HS, Brites RD, Neves LC (2013) In situ measured cross section geometry
495 of old timber structures and its influence on structural safety, *Materials and Structures* 46, pp
496 1193–1208, DOI 10.1617/s11527-012-9964-5

497 Macchioni N (2010) Species identification. In: Kasal B, Tannert T (eds) *In situ assessment of*
498 *structural timber*. RILEM State of the Art Report. Springer, Nederland, pp 105–107.

499 Moşoarcă M, Gioncu V (2013) 3.2.Historical wooden churches from Banat Region, Romania.
500 Damages: Modern consolidation solutions, *Journal of Cultural Heritage*, Vol. 14, pp e45-e59,
501 <https://doi.org/10.1016/j.culher.2012.11.020>

502 Palladio A (1570) *I Quattro Libri dell'Architettura*. Domenico de' Franceschi. Venezia.

503 Parisi M A, Chesi C, Tardini C, Piazza M, (2008). Seismic vulnerability and preservation of
504 timber roof structures. In: *Proceedings SAHC08*, Bath, UK, pp. 1253-1260.

505 Parisi MA, Chesi C, Tardini C, Vecchi D (2017), Seismic vulnerability of timber roof structures:
506 an assessment procedure, *Proceedings 16th World Conference on Earthquake Engineering*,
507 n. 4397, Santiago, Chile.

508 Parisi MA, Piazza M. (2000) Mechanics of plain and retrofitted traditional timber connections.
509 *Journal of Structural Engineering ASCE* 126(12) pp 1395–403.

510 Parisi MA Piazza M, (2002) Seismic behavior and retrofitting of joints in traditional timber roof
511 structures, in *Soil dynamics and Earthquake Engineering*, vol. 22, pp.1183-1191

512 Parisi MA, Piazza M (2015) Seismic strengthening and seismic improvement of timber
513 structures. In *Construction and Building Materials*, vol. 97, pp. 55-66,
514 DOI:10.1016/j.conbuildmat.2015.05.093. pp.55-66.

515 Parisi M. A., Riggio M., Tardini C., Piazza M. (2010) Rehabilitation of Timber Structures and
516 Seismic Vulnerability: a Case Study, *Advanced Materials Research*, Trans Tech
517 Publications, Vol. 134, pp 741-746, DOI:10.4028/www.scientific.net/AMR.133-134.741,
518 URL:www.scientific.net/AMR.133-134.741.pdf

519 Parisi MA, Tardini C and Maritato E (2016) Seismic behaviour and vulnerability of church roof
520 structures. In *Structural Analysis of Historical Constructions: Anamnesis, Diagnosis,*
521 *Therapy, Controls* (Van Balen K and Verstrynghe E (eds)). CRC Press Taylor and Francis.
522 London, UK, pp. 1582-1589.

523 Parisi MA, Tardini C and Vecchi D (2017) A database construction tool for seismic vulnerability
524 assessment of timber roof structures. In *Proceedings of the 4th International Conference on*
525 *Structural Health Assessment of Timber Structures*, Istanbul.Turkey pp 451-462.

526 Petrovski J et al. (1984) Development of Empirical and Theoretical Vulnerability and Seismic
527 Risk Models. In *Proceedings of the 8th World Conference Earthquake Engineering*. Prentice
528 Hall, San Francisco, USA. 1: 433-440

529 Piazza M and Riggio M (2008) Visual strength-grading and NDT of timber in traditional
530 structures. *Journal of Building Appraisal* 3: 267-296. <https://doi.org/10.1057/jba.2008>.

531 Riccadonna D., Giongo I., Casagrande D., Piazza M., (2019) Acoustic Testing for the
532 Preliminary Assessment of Timber Beams - A Pilot Study, *International Journal of*
533 *Architectural Heritage*, <https://doi.org/10.1080/15583058.2019.1598516>

- 534 Riggio M, Tomasi R and Piazza M (2012) Refurbishment of a traditional timber floor with a
535 reversible technique: importance of the investigation campaign for design and control of the
536 intervention, *International Journal of Architectural Heritage*, 8:1, 74-93, DOI:
537 10.1080/15583058.2012.670364
- 538 Riggio M, Anthony RW, Augelli F et al. (2014) In-situ assessment of structural timber using non-
539 destructive techniques. *Materials and structures* 4(47): 749-766.
540 <http://dx.doi.org/10.1617/s11527-013-0093-6>.
- 541 Riggio M, Sandak J and Franke S (2015a) Application of imaging techniques for detection of
542 defects, damage and decay of timber structures on-site. *Construction and Building Materials*
543 101: 1241-1252. <http://dx.doi.org/10.1016/j.conbuildmat.2015.06.065>.
- 544 Riggio M, Parisi MA, Tardini C et al. (2015b) Existing Timber Structures: Proposal for an
545 Assessment Template. In *Proceedings of the 3rd International Conference on Structural
546 Health Assessment of Timber Structures* (Jasieńko J and Nowak T (eds)). Dolnośląskie
547 Wydawnictwo Edukacyjne. Wrocław, Poland, 1: 100-107.
- 548 Riggio M, D'Ayala D, Parisi MA and Tardini C (2018) Assessment of heritage timber structures:
549 Review of standards, guidelines and procedures. *Journal of Cultural Heritage* 31: 220-235.
550 doi 10.1016/j.culher.2017.11.007.
- 551 Sandi H (1986) Vulnerability and Risk Analysis for Individual Structures and Systems, in
552 *Proceedings of the 8th European Conference on Earthquake Engineering*, Lisbon, Portugal,
553 vol. 7, pp 11–69.
- 554 Šobra K, de Rijk R, Aktaş YD, Avez C, Burawska I, Branco JM (2016) Experimental and
555 Analytical Assessment of the Capacity of Traditional Single Notch Joints and Impact
556 of Retrofitting by Self-tapping Screws. In: Cruz H., Saporiti Machado J., Campos
557 Costa A., Xavier Candeias P., Ruggieri N., Manuel Catarino J. (eds) *Historical
558 Earthquake-Resistant Timber Framing in the Mediterranean Area. Lecture Notes in
559 Civil Engineering*, vol 1. Springer, Cham, DOI https://doi.org/10.1007/978-3-319-39492-3_30
- 560
- 561 Sousa HS, Branco JM, Lourenço PB (2014) Characterization of cross-sections from old
562 chestnut beams weakened by decay, *International Journal of Architectural Heritage*, Vol.8,
563 Issue 3, pp. 436-451.
- 564 Tampone G (2016), *Atlante dei dissesti delle strutture lignee – Atlas of the failures of timber
565 structures*, ISBN 9788840443751, Nardini editore,
- 566 Tannert T., Anthony R., Kasal B., Kloiber M., Piazza M., Riggio M., Rinn F., Widmann R.,
567 Yamaguchi N., (2014) In situ assessment of structural timber using semi-destructive
568 techniques, *Materials and Structures*, vol. 47, pp. 767-785 (Test recommendations for
569 selected semi-destructive testing techniques as developed by members of the RILEM
570 Technical Committee AST 215 “In-situ assessment of structural timber”)
- 571 UNI 11035-2:2010: Visual Strength Grading Rules and Characteristic Values for Italian Timber
572 Population. Ente Nazionale Italiano di Unificazione, Milano, Italy
- 573 UNI 11118:2004: Cultural Heritage – Wooden Artefacts – Criteria for the identification of the
574 Wood Species. Ente Nazionale Italiano di Unificazione, Milano, Italy.
- 575 UNI 11119 (2004) Cultural Heritage - Wooden Artefacts - Load bearing structures: on-site
576 inspections for the diagnosis of timber members. Ente Nazionale Italiano di Unificazione,
577 Milano, Italy.
- 578
- 579
- 580
- 582
- 583

584 **Figure captions**

585 Figure 1. Guided survey form for vulnerability assessment, software version.

586 Figure 2. Queen post truss with potentially unstable layout.

587 Figure 3. Connections between king post structures.

588 Figure 4. Irregular cross section of the rafter.

589 Figure 5. Biotic decay due to insects.

590 Figure 6. Wedges adopted to recover contact at the rafter (right rafter and purlin)..

591 Figure 7 (a) Rafter-tie beam joint. Connection reinforced with metal heel straps. The head of the
592 tie-beam is built-in and cannot be inspected; (b) Different types of joint reinforcements and
593 vulnerability class (modified from Parisi and Piazza 2002).

594 Figure 8. Collapse due to massive intervention substituting timber trusses with concrete
595 products at Amatrice, Central Italy earthquake, 2016.

596 Figure 9. The roof structure analysed: (a) internal view (b) numerical model with main elements.

597 Figure 10. Detail of the roof structure.

598

599 **Table titles**

600 Table 1 – Grade examples for structural typology

601 Table 2 – Guide for joint assessment

602 Table 3 – Classification of supports

603 Table 4 – Grade reference for state of the structure

604