



Tolerance analysis by static analogy on 2D assemblies with fits and fasteners

Antonio Armillotta¹

Received: 26 October 2022 / Accepted: 4 May 2023
© The Author(s) 2023

Abstract

In tolerance analysis, the effect of clearance fits is especially difficult to estimate because the mating parts are not necessarily in actual contact and can take an infinite number of relative positions. The treatment of these situations is allowed in most of the available methods, possibly introducing additional elements in the dimension chains with appropriate statistical assumptions. The paper provides a similar extension for the static analogy, a previously proposed method that converts the tolerance analysis problem into an equivalent problem of force analysis. The procedure represents each fit, possibly between patterns of features (e.g., fasteners and holes), with a proper constraint in the equivalent static model. The ability of the constraint to transmit forces and torques is determined according to the types and directions of misalignments allowed by the joint clearance. With simple rules, this avoids complications in the static model, which must include only the constraint between parts rather than the geometric details of the mating features. The extended method, currently limited to 2D dimension chains, is demonstrated on examples involving both dimensional and geometric tolerances. The comparison with existing methods shows the correctness of the proposed procedure. The simplicity of the workflow confirms the possibility, already demonstrated for the static analogy, of avoiding numerical simulations or even the use of computer-based tools.

Keywords Tolerancing · GD&T · Stackup analysis · Dimension chain · Joint clearance · Assembly shift

1 Introduction

A mechanical assembly is designed to ensure functions involving interaction between parts; examples include the positioning of machine elements, the transmission of force or motion, and the sealing of closures. These can be affected by the stackup of part deviations due to uncertainty sources in the manufacturing process. Such situations are detected by tolerance analysis [1]. One or more functional requirements are identified and expressed as geometric entities, such as distances or angles between features of different parts. Each requirement is associated with a chain of dimensions involving features of individual parts. Given the tolerances on part features, the analysis calculates the stackup of part deviations and estimates the resulting variation on the requirement.

Tolerance analysis can be carried out with several methods, which are suitable for problems with assumptions of varying complexity [2]. Part dimensions involved in a functional requirement may be parallel (1D stackup) or variously oriented in plane or space (2D–3D stackup). Specifications on part features may include geometric tolerances in addition to plus-minus dimensional tolerances. The deviations allowed by tolerances may have various types of statistical distributions (normal, beta, etc.), which may span equal or different fractions of the specified tolerances. In an effort to adapt to several possible assumptions, the available methods use complex mathematical models that can only be solved with the help of software tools.

One of the aspects that make tolerance analysis complex is the presence of clearance fits at joints between parts (e.g., shaft–hole or tab–slot) or with fasteners (bolts, screws, dowels, rivets, etc.). In addition to transmitting their geometric deviations, the mating parts can undergo relative linear or angular displacements within the limits allowed by the joint clearance. These further deviations should be included in the dimension chain, but this can be difficult because they have randomly varying directions. Furthermore, fasteners

✉ Antonio Armillotta
antonio.armillotta@polimi.it

¹ Dipartimento Di Meccanica, Politecnico Di Milano, Via La Masa 1, 20156 Milan, Italy

are often installed in patterns and therefore can significantly increase the number of parts involved in a functional requirement; this can make stackup calculations even more difficult.

In 1D stackup problems, joint clearances are treated using the concept of assembly shift [3]. The assembly shift between two mating parts is an auxiliary dimension which corresponds to the random deviation from their relative position due to the clearance. The shift has zero mean and a tolerance depending on the worst-case tolerance limits of the mating features. The advantage of such a definition is that the mating dimensions (e.g., diameters of shafts and holes) do not have to be explicitly added to the dimension chain, as they only determine the tolerance limits on the assembly shift. This is especially useful in the presence of fasteners because the dimension chain includes only the designed parts reducing the total number of elements of the stackup model. However, the random direction of the assembly shift does not allow a straightforward extension of the concept to 2D and 3D stackup problems.

This paper proposes a possible treatment of assembly shifts in the tolerance analysis of 2D dimension chains. The approach is based on a static analogy previously proposed for generic assemblies [4] and mechanisms [5, 6]. The method estimates the linear contributions of the dimensions to the functional requirement (sensitivities) through an equivalent force analysis model. Depending on the complexity of the assembly, this allows for a resolution of tolerance analysis problems through simple force calculations or software tools for structural analysis. As discussed in the following, the sensitivities of the requirement to the assembly shifts can be easily calculated by static analogy without the need to pre-define a statistical distribution of the displacement directions between the parts.

The remainder of the paper is structured as follows. Section 2 recalls the methods available for tolerance analysis problems, with focus to those considering sensitivities and joint clearances. Section 3 recalls the static analogy, while Section 4 describes its extension to stackup problems involving fits and fasteners. Section 5 applies the method to some examples, comparing the results of the static analogy with known methods of tolerance analysis. Section 6 discusses the advantages and limitations of the proposed method. Section 7 demonstrates the application of the method to a more realistic case. Section 8 summarizes the contribution of the work.

2 Literature review

Tolerance analysis has been extensively studied during the past decades. Classifications and in-depth discussions of the available results are provided in the main reviews on the topic [1, 2, 7–10]. In the following, a few references will be

made on the methods based on the same assumptions of this paper. The parts are rigid and designed with dimensional and geometric tolerances on their features. The assembly is created with simple contact relationships between part features (lower kinematic pairs), which determine the position and orientation of the parts without overconstraints. The tolerance analysis is done in a given configuration of the assembly, which may coincide with one of the possible poses of a mechanism.

2.1 Tolerance analysis methods

The core of any tolerance analysis method is a mathematical model of how geometric deviations on part features propagate to the connected parts causing variation on an assembly-level functional requirement. In 2D or 3D stackup problems, such propagation occurs along one or more degrees of freedom (DOFs) allowed by the contact relationships.

Most of the available models associate the requirement with a chain of geometric relations between part features. Once a local coordinate system is associated with each feature, a vector or matrix representation is built for the small displacements allowed by the tolerances; these are a subset of six possible translations and rotations, which excludes those corresponding to invariant DOFs. A geometric transformation (e.g., sum of vectors, product of matrices) is finally used to calculate the propagation of the small displacements along the chain, which determines the deviation on the functional requirement. Different types of representation and transformation have resulted into several tolerance analysis methods. These include the variational model [11–14], the vector loop model [15–17], the small displacement torsor [18, 19], the matrix model [20, 21], the Jacobian model [22], and the Jacobian-torsor model [23–25]. They are too complex to be solved by manual or spreadsheet-based calculations, but suitable for integration into CAD-based software; possible issues related to CAD data transfer are dealt with in [26–28].

More complex representations of geometric deviations, not yet developed at the same level of implementation, have been proposed in order to overcome some limitations of the above methods. The convex-hull methods try to reach full compliance with current tolerancing standards. For this purpose, they represent each tolerance zone by a volume in an appropriate displacement space depending on the type of feature; the volumes are transformed and composed by appropriate operations (e.g., Minkowski sums) to calculate the stackup of tolerances. The main methods based on this principle are the T-maps [29, 30] and the deviation domain [31, 32]. The skin model shapes method aims to account for the effect of form deviations, which are usually neglected in stackup calculations; this is achieved by the generation and the simulated assembly of surface meshes with systematic and random deviations [33–36]. Hybrid approaches have

also been proposed to integrate skin model shapes into other tolerance analysis methods [37, 38].

2.2 Statistical analysis and sensitivities

Once a suitable propagation model of geometric deviations is set up, the analysis may be completed by calculating the deviation limits on the requirement from the specified tolerances (worst-case analysis). Such limits are often an unrealistic estimate of the variation because they do not take into account the compensation of deviations on different parts or the acceptance criteria adopted in statistical process control. For this reason, a more common objective is to estimate the parameters of the statistical distribution of the requirement from the corresponding parameters of part deviations (statistical analysis).

In 1D stackup problems, the dimension chain is linear. In the assumption of normal distributions without mean shifts, statistical tolerance analysis is as simple as the root-sum-square (RSS) stackup equation, i.e., the sum of the variances of independent variables (e.g., [39]). With different distributions, the RSS equation is corrected or replaced by more complex stackup models (see detailed discussion in [40]). Nonlinear dimension chains of 2D–3D stackup problems are treated by further methods reviewed in [8]. Among these, Monte Carlo simulation [41–43] is praised as especially accurate and implemented in most CAD-based tools for tolerance analysis. Quasi-Monte Carlo methods have also been proposed to get comparable accuracy with reduced computational effort [44–46].

A simpler approach to the statistical analysis of 2D–3D tolerance stacks is linearization. This consists in using the RSS equation with stackup coefficients (sensitivities) calculated as first-order approximations of nonlinear dimension chains. As most tolerance analysis methods require Monte Carlo simulation, the linearization is usually done with a sensitivity analysis based on the finite difference method (changing one tolerance at a time and recalculating the output variation, e.g., [47, 48]); however, even more simulation runs are required with a further increase of computational effort. This is avoided by direct linearization, which calculates the sensitivities by means of matrix equations deriving from the 2D–3D modeling of the dimension chain. This approach, however, is currently feasible only in the vector loop model, although recent studies are trying to extend it to other tolerance analysis methods [49–51].

2.3 Joint clearances

The need to deal with joint clearances has been recognized in the development of most tolerance analysis methods. The additional deviations due to clearance fits are generally treated as additional variables in the stackup model. This

is straightforward in 1D problems because the relative displacement between the mating features (assembly shift) is along the direction of the dimension chain [3, 52]. In 2D–3D problems, the displacement is usually in an unknown direction, which must be calculated or randomly generated.

Some methods handle joint clearances in their original formulation (e.g., Jacobian-torsor) or in later extensions. For the variational model, the formulation proposed in [13] includes assembly deviations between parts; cases involving multiple fasteners are addressed in [53] by setting small-displacement matrices from a preliminary study of allowed displacement regions. Extensions for joint clearances have also been suggested for the vector loop model [54, 55], for the Jacobian model [56], and for the T-maps [57]. Problems with joint clearances have also been solved with methodologies deriving from the kinematic analysis of mechanisms, such as the Denavit–Hartenberg model [58, 59] and the screw theory [60, 61].

2.4 Statics-based approach

As mentioned, external forces may influence misalignments at joints. The problem is well known in the assembly simulation of parts with geometric errors. Different loading conditions can change the effective contact points between parts causing additional rotational errors. These are difficult to estimate, especially when considering form deviations as in the methods based on skin model shapes; in [62], the task is formulated as an optimization problem based on equations of multibody dynamics.

Other studies calculate the effect of external forces on assembly configuration using the principle of virtual works of statics, with specific formulations for spatial linkages [63] and parallel manipulators [64]. The same principle can also allow the calculation of worst-case contact conditions regardless of external forces, as proposed for spatial linkages [65] and mechanisms with prismatic joints [66].

A similar approach has proved useful in the tolerance analysis of closed-loop spatial mechanisms (e.g., parallel kinematics machines), where the equations of direct kinematics cannot be differentiated in closed form to get the sensitivities of an output function to the individual generalized coordinates. In [67], the problem is solved by applying unit forces along the different DOFs to the tool center point and calculating the sensitivities from the internal forces on the links.

The above results have suggested a static analogy for solving tolerance analysis problems on generic assemblies. The method proposed in [4] demonstrates the correspondence between internal forces and sensitivities for a wide range of part geometries and joint types. This allows a statistical analysis with direct linearization, reducing the computational effort compared to methods based on Monte Carlo

simulation. With some extensions, the analogy has later been applied to planar linkages [5] and gear trains [6].

The objective of this paper is a further extension of the static analogy for the tolerance analysis of 2D assemblies with joint clearances. Unlike previous methods, force analysis is not used to calculate the relative position of mating features. Rather, it directly calculates the sensitivity of the assembly shift (a 2D version of the concept introduced in [3]) by assuming random directions and lengths of the small displacements allowed by the clearance. As will be discussed below, this approach can considerably streamline the analysis of assemblies containing multiple fasteners.

3 Background on static analogy

In a tolerance analysis problem, a chain of dimensions X_i ($i = 1, \dots, n$) on individual parts determines an assembly-level dimension Y , which represents the functional requirement. The stackup equation is the linear (or linearized) relationship between the requirement and the dimensions:

$$Y = \sum_{i=1}^n S_i X_i \tag{1}$$

where $S_i = \partial Y / \partial X_i$ is the sensitivity of Y to X_i . The dimensions have a random variation specified as

$$X_i = X_{0i} \pm T_i \tag{2}$$

where X_{0i} are the nominal dimensions and T_i are the dimensional tolerances. These can be either assigned to dimensions on part drawings or determined by conversion of geometric tolerances as suggested in [3, 52]. Under this assumption, the nominal value of the requirement is given by

$$Y_0 = \sum_{i=1}^n S_i X_{0i} \tag{3}$$

while the variation of the requirement can be calculated with the corrected root-sum-square (RSS) equation:

$$T_Y = c \sqrt{\sum_{i=1}^n S_i^2 T_i^2} \tag{4}$$

where $c \geq 1$ is a correction factor that accounts for possible violations of the statistical properties assumed on the actual dimensions of manufactured parts (independence, normal distributions, no mean shifts, equal and sufficiently high process capabilities).

The static analogy [4] is a method for calculating the sensitivities in (1) and thus allowing the calculation of output variation using (4). The analogy defines an equivalent problem of force analysis, where two opposite external forces F are applied

to the same parts and along the same direction of dimension Y . If the assembly is exactly constrained, the forces acting on the individual parts can be calculated by solving free-body diagrams. This gives the internal forces F_i corresponding to dimensions X_i . According to considerations deriving from the virtual work principle, the sensitivities are finally calculated as

$$S_i = \frac{F_i}{F} \tag{5}$$

The above correspondence applies to linear dimensions. For angular dimensions, forces in (5) are replaced by torques. If an internal force F_i corresponds to a dimension that is a function $f(X_i)$ of one of the tolerated dimensions, the chain rule allows to transform the sensitivity of (5):

$$S_i = \frac{\partial Y}{\partial X_i} = \frac{\partial Y}{\partial f} \frac{\partial f}{\partial X_i} = \frac{F_i}{F} \frac{\partial f}{\partial X_i} \tag{6}$$

For example, Fig. 1a shows a circular part connected with a V-shaped support. Suppose that the requirement to be controlled is the horizontal distance Y between the left side of the support and the rightmost end of the circle. For such a simple case, an explicit equation can be readily found to calculate Y from three part dimensions: the diameter A of the circle, the angle B of the groove, and the distance C between the root of the groove and the left side of the support:

$$Y = \frac{A}{2} \left(1 + \frac{1}{\tan(B/2)} \right) + C \tag{7}$$

The deviations on A , B , and C contribute to the deviation on Y with the following sensitivities:

$$S_A = \frac{\partial Y}{\partial A} = \frac{1}{2} \left(1 + \frac{1}{\sin B} + \frac{1}{\tan B} \right) \tag{8}$$

$$S_B = \frac{\partial Y}{\partial B} = -\frac{A}{2(1 - \cos B)} \tag{9}$$

$$S_C = \frac{\partial Y}{\partial C} = 1 \tag{10}$$

The same results can be obtained with the static analogy. In the equivalent static model in Fig. 1b, the assembly is loaded with opposite forces F , which have the same direction as Y (horizontal) and act on the points where Y is defined. As the assembly is exactly constrained, the internal forces can be calculated by applying equilibrium equations on free-body diagrams of the two parts (Fig. 1c), where all the constraints are regarded as bilateral. Each dimension is then associated with an internal force F_i , which is eventually used to calculate the sensitivity S_i .

The circle is subjected to the three radial tensile forces F , $F/\sin B$, and $F/\tan B$. Therefore




Fig. 1 Example of static analogy: (a) assembly layout, (b) equivalent static model, (c) free-body diagrams

$$S_{A/2} = \frac{1}{F} \left(F + \frac{F}{\sin B} + \frac{F}{\tan B} \right) = 1 + \frac{1}{\sin B} + \frac{1}{\tan B} \quad (11)$$

The sensitivity associated with the diameter is then obtained from (11) using the chain rule (6):

$$S_A = \frac{1}{2} S_{A/2} = \frac{1}{2} \left(1 + \frac{1}{\sin B} + \frac{1}{\tan B} \right) \quad (12)$$

On the support, the sensitivity of Y to angle B corresponds to the bending moment M_B at the internal node of the frame. This is equal to the bending force $F/\sin B$ multiplied by its moment arm:

$$S_B = \frac{M_B}{F} = \frac{1}{F} \left(-\frac{F}{\sin B} \cdot \frac{A}{2 \tan(B/2)} \right) = -\frac{A}{2(1 - \cos B)} \quad (13)$$

The sensitivity of Y to distance C corresponds to the tensile force F :

$$S_C = \frac{F}{F} = 1 \quad (14)$$

4 Methods

The static analogy must be extended with further assumptions and procedures in order to tackle more complex problems of tolerance analysis involving fits and fasteners. This section introduces the needed extensions and recalls alternative methods that will be used later to validate them on some examples.

4.1 Treatment of 2D assembly shifts

In a planar assembly, parts have contact relationships through their features. These are 2D lines or curves corresponding to surfaces that are perpendicular to the plane. It is often assumed that the contact relationships, specified in the assembly drawing on the nominal geometry of the parts, are preserved in the presence of geometric deviations resulting from manufacturing errors. Consequently, the functional requirement to be analyzed can be expressed as a chain of dimensions (i.e., distances between features) on individual parts.

In many cases, however, the assembly includes situations that do not satisfy the above assumption. These arise in the presence of clearance fits between features of size, where a hole on one part is connected to either a shaft on another part or a fastener. In a fit relationship, the centers of the two features have a random relative displacement (assembly shift) due to the inability to make the two features exactly concentric during the assembly operation. This displacement should be regarded as an additional source of variation, which in turn depends on the variation of the sizes of the mating features, e.g., the diameters D and d of the hole and the shaft/fastener.

As a first approach to take into account the assembly shift in tolerance analysis, D and d could be explicitly added to the dimension chain. This would allow to use the static analogy assuming a given contact relationship between the two features. For example, the shift s in the shaft–hole pair in Fig. 2 can be analyzed by assuming a contact between the features at a given point (as the worst case for the shift). In the equivalent static model, two opposite forces F are applied at the centers




Fig. 2 Static analogy assuming a given contact relationship

of the shaft and the hole. The free-body diagrams show the internal force between shaft and hole, which is equal to F . This force is associated to the radii of the two features: a tensile force for $D/2$ and a compressive force for $d/2$. According to the chain rule, the sensitivities on the two diameters are

$$S_D = \frac{1}{2}S_{D/2} = \frac{1}{2}\frac{F}{F} = \frac{1}{2}, S_d = \frac{1}{2}S_{d/2} = \frac{1}{2}\frac{(-F)}{F} = -\frac{1}{2} \tag{15}$$

As can be easily verified with an explicit equation, the worst-case variation of the shift in the conditions of Fig. 2 is therefore

$$s' = s'_0 \pm T'_s = \frac{D_0 - d_0}{2} \pm \frac{T_D + T_d}{2} \tag{16}$$

This result is true whenever a contact point can be identified for the two features as a result of either the assembly operation or operating conditions. This usually occurs on structures subject to external forces or mechanisms that transmit motion in given directions [4]. In these cases, the shift has a systematic component as in (16) because the two features are necessarily misaligned in order to reach contact at a point.

In a generic assembly, however, the assembly shift does not satisfy the above condition because the parts are not necessarily in actual contact (e.g., due to the presence of lubricant in a rotational pair or to friction in a joint with threaded fasteners). Therefore, the assembly shift has zero average, corresponding to perfect concentricity between the two features (which implies no contact at all). As shown in Fig. 3, the tolerance on the shift in a generic direction is the distance between the ideal condition and two limit conditions of contact on opposite sides. Furthermore, the worst case for the shift is the least material condition (LMC) for both features. This gives the following expression, the same as the one used in [3] for 1D dimension chains:

$$T_s = \frac{D_{LMC} - d_{LMC}}{2} \tag{17}$$

Another difficulty with the above approach is related to the increase of the number of dimensions to be dealt with in the tolerance analysis problem. In an assembly with many




Fig. 3 Actual limits of a 2D assembly shift

fasteners, the dimension chain should include all diameters of the holes and fasteners. Consequently, the static model would be more complex, and possibly difficult to solve due to overconstraining (there are more fasteners than would be needed to constrain the three relative DOFs of the connected parts). It is therefore appropriate to look for a way to simplify the dimension chain and the equivalent static model.

The proposed method does not explicitly add D and d to the dimension chain, but represents their effect with an additional dimension (the assembly shift s) with zero mean and equal bilateral tolerance given by Eq. (17). This choice corresponds to what is done in a 1D stackup problem, with the difference that more than one shift may have to be considered in a 2D problem. In general cases, there are three possible shifts, two translations and one rotation. Yet, it is often recognized that the requirement depends on only two shifts or even one. This depends on how the clearance influences the relative motion of the parts and the requirement itself; this is to be evaluated in advance on each different case. For example, the symmetry of the parts can make an angular shift irrelevant, or the requirement can turn out to be indifferent to a linear shift in one of the possible directions. When in doubt about the direction corresponding to the worst case for the requirement, the direction of a linear shift can be chosen arbitrarily; the static analogy will ensure that shifts in different directions have different effects on the requirement. In any case, there is no need to identify a given contact condition consistently with the above discussed assumptions.

Once appropriate assembly shifts have been identified as additional dimensions, the sensitivity of the requirement to each shift is calculated using the static analogy. For this purpose, the assembly is simplified by replacing each pair of mating features with a joint located at a representative point, e.g., the center of either the original features or one of the fasteners in a pattern. The joint has a number of DOFs which can vary in different situations. Without excluding special cases, a single shaft–hole pair or (less frequently) a single fastener is represented by a constraint with a rotational DOF, while a pattern of fasteners corresponds to a fixed constraint without relative DOFs. In the static model, the joint transmits a corresponding set of forces and torques, which exactly match the linear or angular shifts.

Following the above criterion, any joint that allows translational and rotational misalignments can be correctly represented in the equivalent static model. For example, Fig. 4a shows the case of an anti-rotation pin fit to a D-shaped hole in a bushing. If involved in a functional requirement, the fit can be represented by the common center of the two features and by selecting two of the three possible assembly shifts s_1 , s_2 , and s_3 . As shown in Fig. 4b, the respective tolerances are calculated from the limit dimensions as in (17). For an irregularly shaped pin and hole, the further difficulty is that the LMC conditions depend on the tolerance schemes specified for the two parts. Figure 4c considers three possible cases of profile tolerances:




Fig. 4 Assembly shifts for an irregular-shape fit

all-around, with datum at regardless of feature size (RFS), and with datum at maximum material condition (MMC).

The static model is finally solved by applying the equilibrium conditions to the free-body diagrams of the parts. This provides the internal forces and torques transmitted through each of the joints. The sensitivity of each assembly shift is calculated again from (5), where F_i is the corresponding internal force or torque. As the shifts have zero mean, their sensitivities are always assumed positive irrespective of the direction of F_i .

4.2 Validation

The correctness of the proposed method based on static analogy is verified in comparison with other proven methods for tolerance analysis. These must allow the computation of sensitivities in 2D problems including linear and angular dimensions as well as assembly shifts.

If the dimension chain is simple enough, the functional requirement can be expressed with an explicit stackup equation such as (7) for the example in Section 3. The shifts can be easily added to the equation taking into account their direction relative to the requirement. Once this is done, the sensitivities of Y to dimensions X_i (including shifts) are calculated as $\partial Y / \partial X_i$, and generally include one or more nominal dimensions within or outside the chain. The derivatives can be compared with the results of static analogy,

either analytically or numerically for a given set of nominal dimensions.

In more complex problems, the comparison can be made with the variational method of [13], here recalled in its simplified 2D version. Two-axis coordinate frames are established at selected points of the parts; at least two frames are needed for each part at the features in contact with adjacent parts. The functional requirement Y is associated to two of these frames (the end frames). The transformation between the end frames is the result of a chain of transformations spanning all the frames in a suitable sequence. The chain includes two types of transformations expressed by 3×3 homogeneous matrices:

- Nominal transformations T_{ij} , which represent the relative translations and rotations between the coordinate frames when all part dimensions have their nominal values X_{0i} ;
- Small-displacement transformations DT_{ij} , which represent the additional translations and rotations due to random deviations δX_i on the same dimensions, or to assembly shifts between features of adjacent parts.

The transformation matrices have the following typical forms:

$$T_{ij} = \begin{bmatrix} \cos \theta & -\sin \theta & p_1 \\ \sin \theta & \cos \theta & p_2 \\ 0 & 0 & 1 \end{bmatrix}, \quad DT_{ij} = \begin{bmatrix} 1 & -\delta\theta & \delta p_1 \\ \delta\theta & 1 & \delta p_2 \\ 0 & 0 & 1 \end{bmatrix} \quad (18)$$

where p_1 and p_2 are the relative coordinates of the origin of frame j to the origin of frame i , and θ is the angle between an axis of frame j and the corresponding axis of frame i . The corresponding random deviations are δp_1 , δp_2 , and $\delta\theta$.

The transformation matrix between the end frames is the product of the transformation matrices \mathbf{T}_{ij} and \mathbf{DT}_{ij} in an appropriate sequence. Two different products are calculated: a first product \mathbf{T} with the nominal transformations only, and a second product \mathbf{T}' including the small-displacement transformations. The difference $\mathbf{T}' - \mathbf{T}$ gives the deviation δY resulting from the deviations δX_i assumed for part dimensions and assembly shifts. The calculation of Y depends of the geometric definition of the requirement: a linear distance corresponds to the translation between the end frames, while an angular distance corresponds to the rotation between them.

If an expression of the sensitivities is sought, $\mathbf{T}' - \mathbf{T}$ can be calculated analytically; the expression of δY is a sum of linear contributions of the individual δX_i . This can be tedious in cases where many matrices are to be multiplied and should be limited to the elements contributing to Y .

Alternatively, the tolerance analysis problem is solved by Monte Carlo sensitivity analysis. For a sample of parts (usually in the order of tens of thousands), deviations δX_i are randomly generated from normal distributions with means X_{0i} and 3σ tolerance limits equal to T_i . On the whole sample, δY has a normal distribution whose 3σ tolerance limit T_Y is estimated. The simulation is repeated for each sensitivity to be found; in the i -th simulation, all tolerances are set to zero except T_i ; then T_Y is divided by T_i to get an estimate of S_i .

5 Results

The following examples demonstrate the method on 2D dimension chains of increasing complexity. The analysis is limited to the calculation of sensitivities, omitting the use of the RSS equation for stackup calculation. In each example, the results of the static analogy are validated using one of the methods mentioned in Section 4.

5.1 Limit switch on swivel arm

The assembly in Fig. 5 includes a swivel arm, a circular disc, and a frame. The arm can freely rotate about a pin on the frame. The disc is fastened to the arm by four machine screws in a circular pattern and gets in contact with a limit switch on the frame. The functional requirement Y is an angle defining the orientation of the arm when the disc is against the switch. It is easily recognized that Y depends on three linear dimensions on individual parts: A on the frame, B on the arm, and C on the disc.




Fig. 5 Swivel arm assembly

Only dimensional tolerances T_A , T_B , and T_C are specified on the three dimensions, neglecting other geometric deviations such as the eccentricity of the hole pattern to the outer profile of the disc. In addition, two assembly shifts are considered in the horizontal direction: the linear displacement s_1 of the hole in the arm with respect to the pin, and the linear displacement s_2 of the holes in the disc to the mating screws (the angular shift has no effect on the requirement). Tolerances T_{s1} and T_{s2} on the two shifts are calculated using Eq. (17) from the LMC conditions of the mating features (hole–pin and holes–screws).

In the equivalent static model of Fig. 6, the hole and the pin are represented by their centers; similarly, the screws are not included in the model and the corresponding hole patterns are represented by their centers. An external torque M is applied to the arm, and an opposite reaction torque on the switch of the frame avoids its rotation due to the pulling force of the disc (the contact between the disc and the frame is bilateral for the purpose of force analysis). The free-body diagrams provide the contact forces between the parts; all these forces have the same direction and equal magnitude




Fig. 6 Equivalent static model for the swivel arm assembly

$$F_{int} = \frac{M}{B \sin Y} \tag{19}$$

Table 1 lists the sensitivities calculated for the dimensions and the shifts from the static analogy. For this purpose, Eq. (5) is used after identifying the internal forces associated to the dimensions:

- Dimension A on the frame is subjected to a compressive force F_{int} between the pin and the switch;
- Dimension B on the arm is subjected to a tensile force equal to the component of F_{int} along the centerline;
- A tensile force F_{int} acts on the radius $C/2$ of the disc, and the sensitivity $\partial Y/\partial C$ associated to the diameter is half the sensitivity $\partial Y/\partial(C/2)$ associated to the radius;
- Shift s_1 corresponds to the internal force F_{int} at the pin-hole pair;
- Shift s_2 corresponds to the internal force F_{int} at the center of the hole pattern.

The above results can be verified using the explicit equation of the dimension chain:

$$A = B \cos Y + \frac{C}{2} + s_1 + s_2 \tag{20}$$

Differentiating (20) gives a relationship between deviations δX_i :

$$\delta A = (\delta B \cos Y_0 - B_0 \sin Y_0 \delta Y) + \frac{\delta C}{2} + \delta s_1 + \delta s_2 \tag{21}$$

hence the following linear expression with the same sensitivities as in Table 1:

$$\delta Y = -\frac{\delta A}{B_0 \sin Y_0} + \frac{\delta B}{B_0 \tan Y_0} + \frac{\delta C}{2B_0 \sin Y_0} + \frac{\delta s_1}{B_0 \sin Y_0} + \frac{\delta s_2}{B_0 \sin Y_0} \tag{22}$$

5.2 Diagonal bar on plate

Figure 7 shows a diagonal bar connected to a plate with two machine screws. The requirement Y is the distance between the top point of the bar and the bottom edge of the plate. To




Fig. 7 Diagonal bar assembly

control the variation of Y , tolerances are specified on some dimensions on the two parts. These include distance B and angle C on the plate, and distances E and H on the bar. In addition to T_B , T_C , T_E , and T_H , the least-material diameters d_{LMC} and D_{LMC} are known for the screws and the holes in the bar. Tolerances on other dimensions (A , G) may apply but do not influence the variation of Y . For simplicity, no geometric tolerance is assumed to be specified.

According to the proposed method, the diameters of the screws and holes do not explicitly appear in the dimension chain. They influence Y through two possible assembly shifts of the holes with respect to the mating screws. The first shift s_1 is a vertical translation (other directions would have been equally acceptable, e.g., along the connecting line of the hole centers). The second shift s_2 is a rotation about the center of the first hole. Tolerances T_{s1} and T_{s2} on the two shifts are calculated from (17) and, for the angular shift, dividing the displacement by a rotation arm equal to the nominal distance G_0 of the two hole centers. No shifts occur between the screws and the plate, which are connected with threaded fits with negligible clearance.

Figure 8 shows the equivalent static model. The hole pattern is represented by the center of the first hole, which is regarded as a fixed joint between the two parts. The structure is loaded with two opposite forces F applied to the features defining the requirement. The free-body diagrams provide the internal forces at the joint, which include a force F and a torque

$$M = Fb = F(E \cos C - H/2 \cdot \sin C) \tag{23}$$

The following internal forces are associated to the dimensions of the chain:

Table 1 Sensitivities for the swivel arm assembly

X_i	X_{0i}	T_i	S_i
A	A_0	T_A	$-1/B_0 \sin Y_0$
B	B_0	T_B	$1/B_0 \tan Y_0$
C	C_0	T_C	$1/2B_0 \sin Y_0$
s_1	0	T_{s1}	$1/B_0 \sin Y_0$
s_2	0	T_{s2}	$1/B_0 \sin Y_0$




Fig. 8 Equivalent static model for diagonal bar assembly

- Distance B on the plate is subjected to a tensile force F between the joint and the bottom edge;
- Angle C on the plate is subjected to a positive (anti-clockwise) torque M at the joint;
- Distance E on the bar is subjected to a tensile force equal to the component of F along the centerline;
- Distance $H/2$ on the bar is subjected to a tensile force equal to the component of F across the centerline; again, the sensitivity $\partial Y/\partial H$ is half the sensitivity $\partial Y/\partial(H/2)$.
- Shift s_1 corresponds to the force F at the joint;
- Shift s_2 corresponds to the torque M at the joint.

$$T_{01} = \begin{bmatrix} 1 & 0 & A_0 \\ 0 & 1 & B_0 \\ 0 & 0 & 1 \end{bmatrix}, DT_{11'} = \begin{bmatrix} 1 & 0 & \delta A \\ 0 & 1 & \delta B \\ 0 & 0 & 1 \end{bmatrix} \quad (24)$$

$$T_{12} = \begin{bmatrix} \cos C_0 & -\sin C_0 & 0 \\ \sin C_0 & \cos C_0 & 0 \\ 0 & 0 & 1 \end{bmatrix}, DT_{22'} = \begin{bmatrix} 1 & -\delta C & 0 \\ \delta C & 1 & 0 \\ 0 & 0 & 1 \end{bmatrix} \quad (25)$$

Each internal force is then used to calculate the sensitivity of Y to the dimension using Eq. (5). The results are shown in Table 2.

The above results are verified using the variational method with analytical derivation. The coordinate frames established on the two parts are shown in Fig. 9a. The requirement Y is the vertical distance between the origins of frames 0 and 4, and results from a chain of transformations illustrated in Fig. 9b. The nominal and small-displacement matrices are set by inspecting the geometric relationships between the coordinate frames:

Table 2 Sensitivities for the diagonal bar assembly

X_i	X_{0i}	T_i	S_i
B	B_0	T_B	1
C	C_0	T_B	$E_0 \cos C_0 - H_0/2 \cdot \sin C_0$
E	E_0	T_B	$\sin C_0$
H	H_0	T_B	$1/2 \cdot \cos C_0$
s_1	0	$T_{s1} = (D_{LMC} - d_{LMC})/2$	1
s_2	0	$T_{s2} = (D_{LMC} - d_{LMC})/2G_0$	$E_0 \cos C_0 - H_0/2 \cdot \sin C_0$




Fig. 9 Verification of sensitivities for the diagonal bar assembly: (a) coordinate systems; (b) chain of transformations

$$T_{23} = \begin{bmatrix} 1 & 0 & 0 \\ 0 & 1 & 0 \\ 0 & 0 & 1 \end{bmatrix}, DT_{23} = \begin{bmatrix} 1 & -\delta s_2 & \delta s_1 \sin C_0 \\ \delta s_2 & 1 & \delta s_1 \cos C_0 \\ 0 & 0 & 1 \end{bmatrix} \quad (26)$$

$$T_{34} = \begin{bmatrix} 1 & 0 & E_0 \\ 0 & 1 & H_0/2 \\ 0 & 0 & 1 \end{bmatrix}, DT_{44'} = \begin{bmatrix} 1 & 0 & \delta E \\ 0 & 1 & \delta H/2 \\ 0 & 0 & 1 \end{bmatrix} \quad (27)$$

The nominal transformation between the end features is

$$T_{04} = T_{01}T_{12}T_{23}T_{34} = \begin{bmatrix} \cos C_0 & -\sin C_0 & A_0 + E_0 \cos C_0 - H_0/2 \cdot \sin C_0 \\ \sin C_0 & \cos C_0 & B_0 + E_0 \sin C_0 - H_0/2 \cdot \cos C_0 \\ 0 & 0 & 1 \end{bmatrix} \quad (28)$$

hence

$$Y_0 = [T_{04}]_{23} = B_0 + E_0 \sin C_0 + H_0/2 \cdot \cos C_0 \quad (29)$$

For a given set of random deviations δX_i , the actual transformation is

$$T'_{04} = T_{01}DT_{11'}T_{12}DT_{22'}T_{23}DT_{23}T_{34}DT_{44'} \quad (30)$$

hence

$$Y_0 + \delta Y = [T'_{04}]_{23} = B_0 + E_0 \sin C_0 + H_0/2 \cdot \cos C_0 + \delta B + (E_0 \cos C_0 - H_0/2 \cdot \sin C_0)\delta C + \sin C_0 \delta E + 1/2 \cdot \cos C_0 \cdot \delta H + \delta s_1 + (E_0 \cos C_0 - H_0/2 \cdot \sin C_0)\delta s_2 \quad (31)$$

Comparing (31) and (29) gives the expression of the output deviation:

$$\delta Y = \delta B + (E_0 \cos C_0 - H_0/2 \cdot \sin C_0)\delta C + \sin C_0 \delta E + 1/2 \cdot \cos C_0 \cdot \delta H + \delta s_1 + (E_0 \cos C_0 - H_0/2 \cdot \sin C_0)\delta s_2 \quad (32)$$

All the sensitivities are equal to those calculated from the static analogy and listed in Table 2.

5.3 Plates with geometric tolerancing

In Fig. 10a, plate 2 is connected to plate 1 with four machine screws in a rectangular pattern. The requirement Y is the distance between the left end of plate 1 and the right end of plate 2. Tolerances T_{h1} and T_{h2} are specified on the diameters D_{h1} and D_{h2} of the holes in the two parts. Composite position tolerances are also specified on the hole centers: pattern-locating tolerances T_{p1} and T_{p2} with datums on edges of the plates, and feature-relating tolerances T_{f1} and T_{f2} to limit deviations on hole positions within patterns. On plate 1, the feature-relating tolerance is set according to the fixed-fastener rule, i.e., it is equal to the difference between the diameters of the hole (D_{h2}) and the screw (d_f) at their maximum material condition (MMC). Profile tolerances T_{w1} and T_{w2} are specified on the right edges of the plates with datums on the corresponding left edges. The size tolerance on the screw is much smaller than those on the holes and is thus neglected.

For the purpose of the analysis, the hole pattern on each part is represented by an abstracted feature that includes the centers of two holes on a diagonal. Geometric tolerances are converted to equal bilateral tolerances on the dimensions shown in Fig. 10b. These include A, B, C (linear distances)

and D (angle) on plate 1, and E, G, I, L, M (distances) and H (angle) on plate 2. Furthermore, three assembly shifts are defined between the holes in plate 2 and the mating screws: horizontal and vertical displacements s_1 and s_2 , and angular displacement s_3 . No shifts are considered on plate 1 as the screws engage with threaded holes with negligible clearance. Table 3 lists the dimensional tolerances as functions of the specified geometric tolerances and nominal dimensions.




Fig. 10 Two-plate assembly: (a) specified tolerances; (b) equivalent dimensions

Figure 11 shows the equivalent static model. Among the endpoints of requirement Y , the one on plate 2 is loaded with a horizontal force F , and the one on plate 1 is fixed both in translation and in rotation. The free-body diagrams provide the support reaction and the internal force between the two parts. These forces allow to calculate the sensitivity

Table 3 Dimensional tolerances and sensitivities for the two-plate assembly

X_i	X_{0i}	$T_i (\pm)$	S_i
A	A_0	$T_A = T_{p1}/2$	1
B	B_0	$T_B = T_{p1}/2$	0
C	C_0	$T_C = T_{f1}/2$	0
D	D_0	$T_D = T_{f1}/2B_0$	$-(M_0 - G_0)$
E	E_0	$T_E = T_{p2}/2$	-1
G	G_0	$T_G = T_{p2}/2$	0
H	H_0	$T_H = T_{f2}/2I_0$	$M_0 - G_0$
I	I_0	$T_I = T_{f2}/2$	0
L	L_0	$T_L = T_{w1}/2$	1
M	M_0	$T_M = T_{w2}/2$	0
s_1	0	$T_{s1} = (D_{h2} + T_{h2} - d_p)/2$	1
s_2	0	$T_{s2} = (D_{h2} + T_{h2} - d_p)/2$	0
s_3	0	$T_{s3} = (D_{h2} + T_{h2} - d_p)/2C_0$	$M_0 - G_0$

for each of the dimensions and shifts in Table 3 from Eq. (5). For this purpose, the internal forces associated with the dimensions of plate 1 are identified as follows:

- A: horizontal tensile force F between the first point of the pattern and the left edge;
- B: no vertical internal force;
- C: no internal force between the diagonal points of the pattern;
- D: negative (clockwise) torque $F(M - G)$.

On plate 2, an internal tensile force F acts between the origin of the pattern and the right edge; this force corresponds to dimension $L - E$, and is used to calculate the sensitivities associated with dimensions E and L from the chain rule:

$$\frac{\partial Y}{\partial E} = -\frac{\partial Y}{\partial(L - E)}, \quad \frac{\partial Y}{\partial L} = \frac{\partial Y}{\partial(L - E)} \tag{33}$$

In detail:

- E: internal force F , regarded as compressive according to (33);
- G: no vertical internal force;
- H: positive (anti-clockwise) torque $F(M - G)$;
- I: no internal force between the diagonal points of the pattern;





Fig. 11 Equivalent static model for the two-plate assembly

- L : internal force F , regarded as tensile according to (33);
- M : no vertical internal force.

The following forces correspond to the assembly shifts of the upper plate:

- s_1 : force F at the first point of the pattern;
- s_2 : no force in the direction of the shift;
- s_3 : torque $F(M - G)$ at the first point of the pattern.

Again, the variational model is used to validate the results in Table 3. Figure 12a shows the six coordinate frames established on the two parts. The requirement Y is the horizontal distance between the origins of frames 0 and 6, and results from the chain illustrated in Fig. 12b. The transformation matrices are

$$T_{01} = \begin{bmatrix} 1 & 0 & A_0 \\ 0 & 1 & B_0 \\ 0 & 0 & 1 \end{bmatrix}, DT_{11'} = \begin{bmatrix} 1 & 0 & \delta A \\ 0 & 1 & \delta B \\ 0 & 0 & 1 \end{bmatrix} \quad (34)$$

$$T_{12} = \begin{bmatrix} \cos D_0 & -\sin D_0 & 0 \\ \sin D_0 & \cos D_0 & 0 \\ 0 & 0 & 1 \end{bmatrix}, DT_{22'} = \begin{bmatrix} 1 & -\delta D & 0 \\ \delta D & 1 & 0 \\ 0 & 0 & 1 \end{bmatrix} \quad (35)$$

$$T_{23} = \begin{bmatrix} 1 & 0 & 0 \\ 0 & 1 & 0 \\ 0 & 0 & 1 \end{bmatrix}, DT_{23} = \begin{bmatrix} 1 & -\delta s_3 & \delta s_1 \cos D_0 + \delta s_2 \sin D_0 \\ \delta s_3 & 1 & -\delta s_1 \sin D_0 + \delta s_2 \cos D_0 \\ 0 & 0 & 1 \end{bmatrix} \quad (36)$$

$$T_{34} = \begin{bmatrix} \cos I_0 & \sin I_0 & 0 \\ -\sin I_0 & \cos I_0 & 0 \\ 0 & 0 & 1 \end{bmatrix}, DT_{4'4} = \begin{bmatrix} 1 & -\delta H & 0 \\ \delta H & 1 & 0 \\ 0 & 0 & 1 \end{bmatrix} \quad (37)$$

$$T_{45} = \begin{bmatrix} 1 & 0 & -E_0 \\ 0 & 1 & -G_0 \\ 0 & 0 & 1 \end{bmatrix}, DT_{5'5} = \begin{bmatrix} 1 & 0 & -\delta E \\ 0 & 1 & -\delta G \\ 0 & 0 & 1 \end{bmatrix} \quad (38)$$

$$T_{56} = \begin{bmatrix} 1 & 0 & L_0 \\ 0 & 1 & M_0 \\ 0 & 0 & 1 \end{bmatrix}, DT_{66'} = \begin{bmatrix} 1 & 0 & \delta L \\ 0 & 1 & \delta M \\ 0 & 0 & 1 \end{bmatrix} \quad (39)$$

The nominal transformation is




Fig. 12 Verification of sensitivities for the two-plate assembly: (a) feature coordinate systems; (b) chain of transformations

$$T_{06} = T_{01}T_{12}T_{23}T_{34}T_{45}T_{56} \tag{40}$$

The actual transformation including the stackup of random deviations δX_i is

$$T'_{06} = T_{01}DT_{11}'T_{12}DT_{22}'T_{23}DT_{23}'T_{34}DT_{44}'T_{45}DT_{55}'T_{56}DT_{66}' \tag{41}$$

The deviation on Y is the appropriate element of the difference of the two transformations:

$$\delta Y = [(T'_{06} - T_{06})]_{13} \tag{42}$$

The above stackup model is used in Monte Carlo simulations for the calculation of sensitivities. For this purpose, nominal dimensions X_{0i} are set to the numerical values listed in Table 4. The sensitivities $(S_i)_{MC}$ are estimated as 90% confidence intervals of the means from 10 runs of the simulation with random samples of 100,000 parts; when no interval is shown, equal estimates are obtained in all runs. Table 4 also lists the sensitivities $(S_i)_{SA}$ from the static analogy. The results are clearly in good agreement between the two methods.

6 Discussion

Some considerations suggested by the above examples help to clarify the contribution of the present study both to the development of the static analogy and with respect to other methods of tolerance analysis.

The treatment of fits and fasteners is needed in any tolerance analysis method because it allows a proper estimation of assembly-level deviations resulting from joint clearances. In previous studies on the static analogy [4–6], it was assumed that the two mating features of size (shaft and hole) are always in actual contact as they have to transmit shear forces between the parts; consequently, the equivalent static model was used to find the sensitivities of the dimensions (e.g., diameters) of the features. The assumption is suitable for the study of truss structures and linkages, whose members invariably exchange forces at the joints. In a generic assembly, however, many types of fits (including those involving most types of fasteners) do not have the function of transmitting shear forces. As a result, features can assume an off-center relative position without coming into contact. The proposed procedure, which extends the 1D concept of assembly shift into 2D tolerance analysis, deals effectively with these cases so that the static analogy could cover a wider range of assembly designs. From this point of view, the examples highlight an interesting feature of the approach: once the correct number of DOFs has been correctly associated with a fit (single or multiple), the sensitivities are provided by the resolution of the equivalent static model without the need to predefine the directions of the individual part deviations.

Table 4 Results of the verification for the two-plate assembly

X_i	X_{0i}	$(S_i)_{SA}$	$(S_i)_{MC}$	Unit
A	50 mm	1	1	mm/mm
B	50 mm	0	0	mm/mm
C	111.8 mm	0	0	mm/mm
D	0.464 rad	$M_0 - G_0 = 70$	69.81–70.09	mm/rad
E	20 mm	1	1	mm/mm
G	20 mm	0	0	mm/mm
H	0.464 rad	$M_0 - G_0 = 70$	69.85–70.07	mm/rad
I	111.8 mm	0	0	mm/mm
L	140 mm	1	1	mm/mm
M	90 mm	0	0	mm/mm
s_1	0	1	1	mm/mm
s_2	0	0	0	mm/mm
s_3	0	$M_0 - G_0 = 70$	69.89–70.09	mm/rad

The proposed extension can therefore be justified as an attempt to increase the completeness of the static analogy, in order to bring its application potential closer to other tolerance analysis methods. Many of these allow a treatment of fits and fasteners, generally with additional elements in the chain of geometric relations, as in the case of the variational model used as a baseline method for the examples. Compared to existing methods, however, the static analogy has some favorable properties with respect to two aspects mentioned in the literature review:

- It allows direct linearization, i.e., evaluates the sensitivities without requiring a finite-difference plan of Monte Carlo simulations. This feature, which helps reduce the computational effort, is seemingly common only to the vector loop model as well as to some approaches for specific types of mechanisms. An easy calculation of sensitivities can streamline any type of stackup analysis (worst-case or statistical) with various assumptions on manufacturing processes (e.g., statistical distributions and process capabilities). It also provides a ready assessment of the relative effects of individual tolerances on the functional requirement.
- It allows in principle a manual or spreadsheet-based solution of the tolerance analysis problem, which is currently only possible in 1D stackup problems. In most 2D cases, static calculations can be done graphically or by solving equilibrium equations; the use of a computer is not strictly necessary and the required knowledge is the same required for force analysis in mechanical design projects. It can be noted that analytical solutions, here sought for comparison purposes, are usually not required in design practice; static calculations would be even simpler if based on numerical values of the forces, which are sufficient to estimate the variation of interest.




Fig. 13 Electric motor assembly

On the critical side, the latter advantage could lead to limitations in some situations. When dealing with very complex assemblies, hand calculations are more complex and can be less convenient than a computer-based method. This is especially true for overconstrained assemblies, for which the static analogy has not yet been proven; in any case, these would generally require the use of finite element analysis software with possible doubts about the effectiveness and simplicity of the workflow.

Furthermore, some difficulties can be expected in perspective of an integration of the static analogy in CAD-based software. Some interactive decisions are needed along the way to solve a tolerance analysis problem. The first one is the setup of the assembly shifts, which requires an understanding of possible misalignments and their potential effects on the functional requirement. The second one is the correct association of dimensions and shifts to internal forces of the equivalent static model. Further work will be needed to prove that these steps can be automated for a full software implementation.

7 Application

The workflow of the static analogy is now demonstrated on a simple realistic case of tolerance analysis. Figure 13 shows the mounting of an electric motor on a fixed frame using a bracket and threaded fasteners. The variation on the functional requirements Y_1 , Y_2 , Y_3 , and Y_4 , indicated on the assembly drawing, is to be estimated. Dimensional and geometric tolerances are specified on the three main parts as detailed in Fig. 14. The




Fig. 14 Parts of the electric motor assembly

Table 5 Tolerances for the electric motor assembly

Tolerance	Unit	Calculation	Value
T_A	mm	0.5/2	0.250
T_B	rad	0.15/60	0.003
T_C	rad	1.5/100	0.015
T_E	mm	$(0.4+2 \cdot 0.2)/2$	0.400
T_G	rad	$(0.4+2 \cdot 0.2)/60$	0.013
T_H	mm	$(0.4+2 \cdot 0.2)/2$	0.400
T_1	mm	$(5.25-4)/2$	0.625
T_2	rad	$(5.25-4)/60$	0.021
T_L	mm	$(0.3+2 \cdot 0.1)/2$	0.250
T_N	mm	$(0.3+2 \cdot 0.1)/2$	0.250
T_P	mm	0.12/2	0.060
T_Q	rad	0.08/25	0.003
T_R	rad	0.08/25	0.003
T_3	mm	$((5.1-4)/2)^2 + ((5.25-4)/2)^2)^{1/2}$	0.851
T_4	mm	$((5.1-4)/2)^2 + ((5.25-4)/2)^2)^{1/2}$	0.851

calculation will neglect any form error and deformation of the parts, as well as the deviations on the diameters of the M4 bolts.

For the purpose of the analysis, the geometric tolerances are translated into equivalent plus-minus tolerances on the linear and angular dimensions shown in Fig. 15. The hole patterns are represented by their centers, and appropriate assembly shifts are defined where needed. For the holes on the horizontal wall of the bracket, s_1 and s_2 are the misalignments with respect to the frame in the longitudinal and angular directions, respectively. For the holes on the flange of the motor, s_3 and s_4 are the misalignments with respect to the bracket in the horizontal and vertical directions, respectively. Table 5 describes the calculation of the tolerances for all the dimensions and the assembly shifts. The tolerances on s_3 and s_4 are the RSS stackup of two terms because the bolts shift with respect to both the bracket and the motor.




Fig. 15 Dimensions and shifts for the electric motor assembly

Figure 16 shows the equivalent static models for the analysis of the four requirements. External forces F are applied to the shoulder of the motor shaft in the directions of Y_1 and Y_3 , while external torques M are applied to the end journal of the same shaft in the directions of Y_2 and Y_4 . The internal forces for each loading are calculated by solving the exactly constrained free-body diagram. Table 6 lists the sensitivities of the requirements with respect to the tolerances.

The RSS equations give the resulting tolerances on the four requirements:

$$T_{Y1} = \sqrt{S_{H1}^2 T_H^2 + S_{N1}^2 T_N^2 + S_{41}^2 T_4^2} = 0.97 \text{ mm} \quad (43)$$

$$T_{Y2} = \sqrt{S_{C2}^2 T_C^2 + S_{Q2}^2 T_Q^2} = 0.015 \text{ rad} = 0.88^\circ \quad (44)$$

$$T_{Y3} = \sqrt{S_{A3}^2 T_A^2 + S_{E3}^2 T_E^2 + S_{13}^2 T_1^2 + S_{P3}^2 T_P^2} = 0.78 \text{ mm} \quad (45)$$

$$T_{Y4} = \sqrt{S_{B4}^2 T_B^2 + S_{G4}^2 T_G^2 + S_{24}^2 T_2^2 + S_{R4}^2 T_R^2} = 0.025 \text{ rad} = 1.44^\circ \quad (46)$$

8 Conclusions

The proposed method has the potential to simplify tolerance analysis on assemblies including fits and fasteners. For this purpose, it integrates the two concepts of assembly shift and static analogy. The assembly shift, commonly used in the analysis of 1D dimension chains, excludes the sizes of mating features (e.g., the diameters of holes, shafts, and fasteners) from the dimension chain; their effect on assembly-level variation is accounted for by an additional zero-mean dimension,




Fig. 16 Equivalent static models for the requirements of the electric motor assembly

whose tolerance is calculated from the LMC dimensions of the features. The static analogy allows the extension of the assembly shift to 2D dimension chains, avoiding the need to predefine the worst-case direction of the misalignment

Table 6 Sensitivities for the electric motor assembly

Sensitivity	Y_1	Y_2	Y_3	Y_4
S_{Ai}	-	-	1	-
S_{Bi}	-	-	-	1
S_{Ci}	-	1	-	-
S_{Ei}	-	-	1	-
S_{Gi}	-	-	-	1
S_{Hi}	1	-	-	-
S_{Ii}	-	-	1	-
S_{2i}	-	-	-	1
S_{Li}	-	-	-	-
S_{Ni}	1	-	-	-
S_{Pi}	-	-	1	-
S_{Qi}	-	1	-	-
S_{Ri}	-	-	-	1
S_{3i}	-	-	-	-
S_{4i}	1	-	-	-

between the features or to simulate the relative position of the two features using more complex mathematical formulations.

Application to some test cases has shown that the method provides correct results in comparison with existing methods. Compared to these, it could provide the following advantages:

- Direct linearization, which avoids Monte Carlo simulation plans;
- Use of procedures deriving from structural analysis, customary in mechanical design, and possibly carried out graphically or with simple manual calculations.

On the other hand, further developments are needed to overcome the following shortcomings:

- Possible difficulties in the application to complex assemblies, which may require more effort to solve the static models;
- Incomplete automation of the procedure, which could require interactive decisions in a possible CAD-based software implementation;
- Current limitation to exactly constrained assemblies with rigid parts;

- Treatment of geometric tolerances through conversion into equivalent dimensional tolerances, without complete coverage of tolerancing standards;
- Need to extend the method to 3D dimension chains, through a broader classification of the force-tolerance correspondences considered in the static analogy.

Funding Open access funding provided by Politecnico di Milano within the CRUI-CARE Agreement.

Data availability The author confirms that the data supporting the findings of this study are available within the paper.

Declarations

Conflict of interest The author declares no competing interests.

Open Access This article is licensed under a Creative Commons Attribution 4.0 International License, which permits use, sharing, adaptation, distribution and reproduction in any medium or format, as long as you give appropriate credit to the original author(s) and the source, provide a link to the Creative Commons licence, and indicate if changes were made. The images or other third party material in this article are included in the article's Creative Commons licence, unless indicated otherwise in a credit line to the material. If material is not included in the article's Creative Commons licence and your intended use is not permitted by statutory regulation or exceeds the permitted use, you will need to obtain permission directly from the copyright holder. To view a copy of this licence, visit <http://creativecommons.org/licenses/by/4.0/>.

References

- Hong YS, Chang TC (2002) A comprehensive review of tolerancing research. *Int J Prod Res* 40(11):2425–2459
- Chen H, Jin S, Li Z, Lai X (2014) A comprehensive study of three dimensional tolerance analysis methods. *Comput Aided Des* 53:1–13
- Fischer BR (2004) *Mechanical tolerance stackup and analysis*. Marcel Dekker, New York
- Armillotta A (2014) A static analogy for 2D tolerance analysis. *Assem Autom* 34(2):182–191
- Armillotta A (2015) Force analysis as a support to computer-aided tolerancing of planar linkages. *Mech Mach Theory* 93:11–25
- Armillotta A (2019) Tolerance analysis of gear trains by static analogy. *Mech Mach Theory* 135:65–80
- Shen Z, Ameta G, Shah JJ, Davidson JK (2005) A comparative study of tolerance analysis methods. *ASME J Comput Inf Sci Eng* 5:247–256
- Singh PK, Jain PK, Jain SC (2009) Important issues in tolerance design of mechanical assemblies. Part I: tolerance analysis. *Proc IMechE B J Eng Manuf* 223:1225–1247
- Schleich B, Wartzack S (2016) A quantitative comparison of tolerance analysis approaches for rigid mechanical assemblies. *Procedia CIRP* 43:172–177
- Cao Y, Liu T, Yang J (2018) A comprehensive review of tolerance analysis models. *Int J Adv Manuf Technol* 97:3055–3085
- Light R, Gossard DC (1982) Modification of geometric models through variational geometry. *Comput Aided Des* 14:209–214
- Gupta S, Turner JU (1993) Variational solid modeling for tolerance analysis. *IEEE Comp Graphics Appl* 13(3):64–74
- Whitney DE, Gilbert OL, Jastrzebski M (1994) Representation of geometric variations using matrix transforms for statistical tolerance analysis in assemblies. *Res Eng Des* 6:191–210
- Wu Y, Chen C (2018) An automatic generation method of the coordinate system for automatic assembly tolerance analysis. *Int J Adv Manuf Technol* 95:889–903
- Chase KW, Gao J, Magleby SP (1995) General 2-D tolerance analysis of mechanical assemblies with small kinematic adjustments. *J Des Manuf* 5:263–274
- Gao J, Chase KW, Magleby SP (1998) Generalized 3-D tolerance analysis of mechanical assemblies with small kinematic adjustments. *IIE Trans* 30(4):367–377
- Yu J, Zhao Y, Wang H, Lai X (2018) Tolerance analysis of mechanical assemblies based on the product of exponentials formula. *Proc IMechE Part B: J Eng Manuf* 232(14):2616–2626
- Bourdet P, Mathieu L, Lartigue C, Ballu A (1996) The concept of the small displacement torsor in metrology. *Ser Adv Math Appl Sci* 40:110–122
- Li H, Zhu H, Li P, He F (2014) Tolerance analysis of mechanical assemblies based on small displacement torsor and deviation propagation theories. *Int J Adv Manuf Technol* 72:89–99
- Salomons OW, Haalboom FJ, Poerink HJJ, Slooten FV, van Houten FJAM, Kals HJJ (1996) A computer aided tolerancing tool II: tolerance analysis. *Comput Ind* 31(2):175–186
- Desrochers A, Rivière A (1997) A matrix approach to the representation of tolerance zones and clearances. *Int J Adv Manuf Technol* 13(9):630–636
- Rivest L, Fortin C, Morel C (1994) Tolerancing a solid model with a kinematic formulation. *Comput Aid Des* 26:465–476
- Laperrière L, Ghie W, Desrochers A (2002) Statistical and deterministic tolerance analysis and synthesis using a unified Jacobian-torsor model. *CIRP Ann Manuf Technol* 51(1):417–420
- Chen H, Jin S, Li Z, Lai X (2015) A modified method of the unified Jacobian-torsor model for tolerance analysis and allocation. *Int J Prec Eng Manuf* 16(8):1789–1800
- Peng H, Chang S (2022) Including material conditions effects in statistical geometrical tolerance analysis of mechanical assemblies. *Int J Adv Manuf Technol* 119:6665–6678
- Li JG, Yao YX, Wang P (2014) Assembly accuracy prediction based on CAD model. *Int J Adv Manuf Technol* 75:825–832
- Sarigecili MI, Roy U, Rachuri S (2014) Interpreting the semantics of GD&T specifications of a product for tolerance analysis. *Comput Aided Des* 47:72–84
- Shi X, Tian X, Wang G (2020) Screening product tolerances considering semantic variation propagation and fusion for assembly precision analysis. *Int J Precis Eng Manuf* 21:1259–1278
- Davidson JK, Mujezinović A, Shah JJ (2002) A new mathematical model for geometric tolerances as applied to round faces. *J Mech Des* 124(4):609–622
- Mujezinović A, Davidson JK, Shah JJ (2004) A new mathematical model for geometric tolerances as applied to polygonal faces. *J Mech Des* 126(3):504–518
- Giordano M, Pairel E, Samper S (1999) Mathematical representation of tolerance zones. *Proc CIRP CAT, Enschede, The Netherlands*
- Teissandier D, Couétard Y, Gérard A (1999) A computer aided tolerancing model: proportioned assembly clearance volume. *Comput Aided Des* 31(13):805–817
- Anwer N, Schleich B, Mathieu L, Wartzack S (2014) From solid modelling to skin model shapes: shifting paradigms in computer-aided tolerancing. *CIRP Ann Manuf Technol* 63(1):137–140
- Schleich B, Wartzack S (2015) Evaluation of geometric tolerances and generation of variational part representatives for tolerance analysis. *Int J Adv Manuf Technol* 79:959–983
- Chan Q, Zhenyu L, Xiang P, Guifang D, Jianrong T (2015) Realistic geometry based feature modeling of complex part and its application in assembly quality analysis. *ASME J Comput Inf Sci Eng* 15:041007

36. Schleich B, Wartzack S (2018) Novel approaches for the assembly simulation of rigid skin model shapes in tolerance analysis. *Comput Aided Des* 101:1–11
37. Liu T, Cao Y, Zhao Q, Yang J (2019) Assembly tolerance analysis based on the Jacobian model and skin model shapes. *Assem Autom* 39(2):245–253
38. Yi Y, Liu X, Liu T, Ni Z (2021) A generic integrated approach of assembly tolerance analysis based on skin model shapes. *Proc IMechE Part B: J Eng Manuf* 235(4):689–704
39. Fortini ET (1967) Dimensioning for interchangeable manufacture. Industrial Press, New York
40. Børke Ø (1989) Computer-aided tolerancing. ASME Press, New York
41. Turner JU, Wozny MJ (1987) Tolerances in computer-aided geometric design. *Visual Comput* 3:214–226
42. Skowronski VJ, Turner JU (1996) Estimating gradients for statistical tolerance systems. *Comput Aided Des* 28:933–941
43. Chongying G, Jianhua L, Ke J (2016) Efficient statistical analysis of geometric tolerances using unified error distribution and an analytical variation model. *Int J Adv Manuf Technol* 84:347–360
44. Cao Y, Yan H, Liu T, Yang J (2016) Application of quasi-Monte Carlo method based on good point set in tolerance analysis. *ASME J Comput Inf Sci Eng* 16:021008
45. Zhu H, Zhou X, Li H (2016) A novel tolerance analysis for mechanical assemblies based on convex method and non-probabilistic set theory. *Int J Adv Manuf Technol* 83:1649–1657
46. Zhou C, Liu Z, Qiu C, Tan J (2021) A quasi-Monte Carlo statistical three-dimensional tolerance analysis method of products based on edge sampling. *Assem Autom* 41(4):501–513
47. Stuppy J, Meerkamm H (2009) Tolerance analysis of a crank mechanism by taking into account different kinds of deviation. *Proc CIRP-CAT Conf, Annecy, France*
48. Walter M, Sprügel T, Wartzack S (2013) Tolerance analysis of systems in motion taking into account interactions between deviations. *Proc IMech E Part B: J Eng Manuf* 227:709–719
49. Ziegler P, Wartzack S (2015) A statistical method to identify main contributing tolerances in assemblability studies based on convex hull techniques. *J Zhejiang Univ Sci A: Appl Phys Eng* 16(5):361–370
50. Chitale AN, Davidson JK, Shah JJ (2019) Statistical tolerance analysis with sensitivities established from tolerance-maps and deviation spaces. *ASME J Comput Inf Sci Eng* 19:041002
51. Schleich B, Wartzack S (2018) An approach to the sensitivity analysis in variation simulations considering form deviations. *Procedia CIRP* 75:273–278
52. Drake PJ (ed) (1999) Dimensioning and tolerancing handbook. McGraw-Hill, New York
53. Polini W (2014) To model joints with clearance for tolerance analysis. *Proc IMechE Part B: J Eng Manuf* 228(12):1689–1700
54. Choi JH, Lee SJ, Choi DH (1998) Tolerance optimization for mechanisms with lubricated joints. *Multibody Sys Dyn* 2:145–168
55. Ramos Barbero B, Aragon AC, Pedrosa CM (2015) Validation of a tolerance analysis simulation procedure in assemblies. *Int J Adv Manuf Technol* 76:1297–1310
56. Zhang L, Nie H, Wei X (2020) Kinematic accuracy method of mechanisms based on tolerance theories. *Math Probl Eng* 5023092
57. Ameta G, Davidson JK, Shah JJ (2007) Generate frequency distributions of clearance and allocate tolerances for pin-hole assemblies. *ASME J Comput Inf Sci Eng* 7:347–359
58. Kim J, Song WJ, Kang BS (2010) Stochastic approach to kinematic reliability of open-loop mechanism with dimensional tolerance. *Appl Math Model* 34:1225–1237
59. Wu W, Rao SS (2007) Uncertainty analysis and allocation of joint tolerances in robot manipulators based on interval analysis. *Reliab Eng Sys Safety* 92:54–64
60. Tsai MJ, Lai TH (2004) Kinematic sensitivity analysis of linkage with joint clearance based on transmission quality. *Mech Mach Theory* 39:1189–1206
61. Kumaraswamy U, Shunmugam MS, Sujatha S (2013) A unified framework for tolerance analysis of planar and spatial mechanisms using screw theory. *Mech Mach Theory* 69:168–184
62. Yan X, Ballu A (2018) Tolerance analysis using skin model shapes and linear complementarity conditions. *J Manuf Sys* 48:140–156
63. Innocenti C (2002) Kinematic clearance sensitivity analysis of spatial structures with revolute joints. *Trans ASME: J Mech Des* 124:52–57
64. Chebbi AH, Affi Z, Romdhane L (2009) Prediction of the pose errors produced by joint clearance for a 3-UPU parallel robot. *Mech Mach Theory* 44:1768–1783
65. Venanzi S, Parenti-Castelli V (2005) A new technique for clearance influence analysis in spatial mechanisms. *Trans ASME: J Mech Des* 127:446–455
66. Parenti-Castelli V, Venanzi S (2005) Clearance influence analysis on mechanisms. *Mech Mach Theory* 40:1316–1329
67. Pott A, Hiller M (2004) A force based approach to error analysis of parallel kinematic mechanisms. In: Lenarčič J, Galletti C, eds., *On Advances in Robot Kinematics*, Springer, Dordrecht

Publisher's note Springer Nature remains neutral with regard to jurisdictional claims in published maps and institutional affiliations.